



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20007343/R1tf3e2-1

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-10-2020



Code : LPC2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDA 9899L	Veh. Inspected	SME 7147J
Policy No.	Z/20/VP026297	Coverage (\$)	0.00
Claim No.	20/20/20/VP05/023471	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	21/09/2020

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA 1.6 GLS	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHD841CMJU741630	Colour	GREY
Odometer	20685	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	6 mm
L/H Front Tyre	195/65 R15	NEXEN	6 mm
R/H Rear Tyre	195/65 R15	NEXEN	6 mm
L/H Rear Tyre	195/65 R15	NEXEN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	14/07/2020	Inspection Date	16/07/2020
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------