

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Fork

Ulu Tiale

Name : Aidil Bin Rahmad

Accident Date : 20-Sep-20

Vehicle No : FBP6870H

Vehicle Model : Honda
NSS300A

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Front fork assy Bent/Hm 750 not allowed	\$ 960.00 ✓
1	Fork under bracket Bent	\$ 200.00 ✓
1	Front fender SNO	\$ 120.00 ✓
1	Front rim R	\$ 600.00 X
1	Front brake disc n1	\$ 130.00 X
1	Front rim shaft Bent	\$ 80.00 ✓
1	Front fender rear (matt black) su	\$ 180.00 X
1	Front side cover - R/L/H (white) Cne	\$ 380.00 ✓
1	Front side inner cover- R/L/H (silver) Cne 145.00	\$ 180.00 ✓
1	Front inner cover - R/H (matt black) cm	\$ 320.00 ✓
1	Handle-bar Bent	\$ 140.00 ✓
1	Handle-bar end (1 set) sca 35	\$ 56.00 ✓
1	Mirror (1 set) cu7	\$ 160.00 ✓
1	Rear side cover - R/H (white) R	\$ 150.00 X
1	Exhaust pipe assy R	\$ 980.00 X
1	Exhaust centre cover (matt black) sca 60	\$ 90.00 ✓
1	Exhaust centre lower cover Bent 95	\$ 120.00 ✓
1	Side stand n1	\$ 50.00 X
1	Main stand n1	\$ 100.00 X
		\$ 4,996.00
	Engine Bar #180 cu7 ✓	
	headlamp assy #650 cra ✓	
	Less 10%	\$ 499.60
		\$ 4,496.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3315
107
2987.5

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : **Aidil Bin Rahmad**

Accident Date : **20-Sep-20**

Vehicle No : **FBP6870H**

Vehicle Model : **Honda
NSS300A**

Estimated Repair Costs

Special Net Items

1	Bearing cone (1 set) Nec	\$ 80.00
		<u>\$ 80.00</u>

S/No. Labour


1	To provide towing service	\$ 11 80.00
2	To check wiring and reset headlamp focusing	\$ 11 120.00
3	To provide paint work	\$ 800.00
4	To provide labour	\$ 500.00
		<u>\$ 1,500.00</u>

Grand Total

\$ 6,076.40

Singapore Dollars: Six Thousand Seventy-Six and Cents: Forty only

3763.5
301e


EROFIA MOTOR TRADING PTE LTD