COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Updated 11 Feb 2020

DATE:

21.09.2020

VEHICLE NO .: SHD3409U

> SAS, Police Report

> COE rebute, Book Value

INSURAN

(Attached)

Total: 10 Pages

MODEL:

HYUNDALIONIQ

INSURANCE: FIRE CASE

MVA: LIM TS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Bonnet	1		\$950.5
	Insulator, Hood	1		\$398.1
	Insulator Clips	10	\$2.20	\$22.0
	Bonnet Rubber	1		\$35.5
	Bonnet Cable	1		\$53.2
	Bonnet Hinge (LH/RH)	2	\$57.70	\$115.4
	Bonnet Lock	1		\$132.6
	Catch, Hood Auxiliary Hook	1		\$8.6
	RADIATOR GRILLE EMBLEM	1		\$438.0
	Radiator Grille Emblem	1		\$88.0
	Front Bumper Cover	1		\$499.9
	Front Bumper Reinforcement	1		\$696.4
	Front Bumper Reinforcement Absorber	1		\$115.7
	Front Bumper Lower Reinforcement Bracket (LH/RH)	2	\$165.00	\$330.0
	Front Bumper Sponge	1		\$78.8
	Front Bumper Centre Grille	1		\$301.9
	Front Bumper Lower Grille	1		\$166.9
	Lamp Assy, FOG (LH/RH)	2	\$920.00	\$1,840.0
	Front Bumper Clips	10		\$22.0
	Front Bumper Side Retainer	2	\$77.00	\$154.0
	Front Lower Crossmember	1		\$357.7
	Front Radiator Lower Support Panel	1		\$357.7
	Front Under Cover	1		\$180.80
	Engine Under Cover (RR)	1		\$457.4
	Front Bumper Top Garnish	1		\$225.4
	Cover, Front Bumper Hole (LH/RH)	2	\$28.38	\$56.7
	Reinforcement, Front Bumper Lower	1		\$236.1
	Bracket, Front Bumper Extension Mounting	1		\$110.4
	Support Fr Bumper, RH	1		\$81.70
	Support Fr Bumper, LH	1		\$81.70
	Front Bumper Centre Frame	1		\$236.90
	Bracket, Front Bumper Side, RH	1		\$82.30
	Bracket, Front Bumper Side, LH	1		\$82.30
	Bracket, Front Bumper Mounting	1		\$29.60
	Bracket, Front Bumper Mounting, No. 2	1		\$97.80
	Absorber, Front Bumper, Lower	1		\$127.70
	Unit Assy, Headlamp, RH (LED)	1		\$3,455.00
	Unit Assy, Headlamp, LH (LED)	1		\$3,455.00
	Head Lamp Panel (RH)	1		\$240.10
	Head Lamp Panel (LH)	1		\$240.10
	Top Panel Centre	1		\$364.98

BURNT

RT NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Top Panel Side LH	1		\$145.90
	Top Panel Side RH	1		\$145.90
	Brace Panel	1		\$75.20
	Bracket, Headlamp Mounting, RH	1		\$25.50
	Bracket, Headlamp Mounting, LH	1		\$25.50
	Radiator Assy	1		\$1,841.80
	Radiator Fan Motor Assy	1		\$661.30
	*Radiator Top Hose, LH	1 1		\$43.03
	*Radiator Top Hose, RH	1 1		\$42.60
	Radiator Spare Tank	'		
	Radiator Bottom Mounting	1 1		\$125.80
	Stay, Radiator Support, RH			\$27.50
	Stay, Radiator Support, LH	1 1	2	\$65.70
	Radiator Fan Blade (RH)			\$65.70
	Radiator Fan Blade (LH)			\$233.10
	Radiator Fan Motor (RH)			\$233.10
	Radiator Fan Motor (LH)			\$543.70
	Deflector, Radiator Side, RH	1		\$543.70
	Deflector, Radiator Side, RH Deflector, Radiator Side, LH	1 1		\$83.50
		1 1		\$83.50
	Cover, Radiator Support Opening	1		\$225.40
	Reserve Tank Assy, Radiator w/o Cap Pipe, Radiator	1		\$395.30
	Button Assy, Horn			\$126.50
	Horn Wire			\$2,377.30
	Horn (1 PC)			\$6,079.70
	Airflow Sensor			\$112.71
	Cleaner Assy, Air			\$517.80
	Air Cleaner Top Cover			\$970.30
	Air Cleaner Bottom Cover			\$446.50
	Air Cleaner Hose			\$947.80
	AIR DUCT CENTRE			\$62.12
	Inlet Assy, Air Cleaner			\$129.40
	Air Duct Centre	'		\$199.20
	Aircon Control Assy	'		\$94.03
	Panel Assy, Instrument Cluster Finish	'		\$867.70
	Valve, Cooler Expansion	'		\$1,536.20
	Thermistor, Cooler, No. 1	'		\$275.80
	Tube & Accessory Assy, Airconditioner	'		\$68.00
	Evaporator Sub-Assy, Cooler, No. 1	'		\$631.90
	Compressor Assy, W/Motor			\$1,229.30
	Condenser Assy, W/Receiver	'		\$2,924.20
	Aircon Discharge Hose	'		\$1,336.60
	Aircon Liquid Hose & Pipe	'		\$386.90
	Aircon Hose Suction			\$580.45 \$540.50
	Aircon Blower Assy		l	\$548.50 \$1.036.00
	Fender Sub-Assy, Front RH	'	1	\$1,036.00
	Fender Sub-Assy, Front LH	'		\$945.30
	Front Housing Assy, LH	'		\$945.30
	Front Housing Assy, RH	¦		\$958.30
	Front Fender Shield LH			\$958.30
	Front Fender Shield RH			\$198.50 \$108.50
	Front Fender Shield ClipS	10	¢2 20	\$198.50
	•	ן יט ן	\$2.20	\$22.00

Surve

NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Fender Hybrid Emblem, LH	1		\$86.50
	Front Fender Hybrid Emblem, RH	1		\$86.50
	Bracket, Front Side Panel, RH	1		\$44.50
	Bracket, Front Side Panel, LH	1		\$44.50
	Extension, Front Fender, RH	1		\$47.20
	Extension, Front Fender, LH	1		\$47.20
	Protector, Front Fender Upper, LH	1		\$46.10
	Protector, Front Fender Side Panel, RH	1		\$113.90
	Seal, Front Fender To Cowl Side, RH/LH	2	\$15.20	\$30.40
	Gusset, Front Fender Apron, Lower RH	1	\$10.20	\$34.90
	Gusset, Front Fender Apron, Lower LH	1		\$34.90
	Extension, Front Fender Apron, Front RH/LH	2	\$23.20	\$46.40
	Member, Front Apron To Cowl Side, Upper RH	1	Ψ20.20	\$138.40
	Member, Front Apron To Cowl Side, Upper LH			\$138.40
	Front Apron To Cowl Side, Lower Frt RH	'		\$82.30
	Front Apron To Cowl Side, Lower Frt LH	'		\$82.30
	Tray, Battery			\$42.80
	Clamp, Battery			\$58.00
	Panel Sub-Assy, Front Door, RH	'		\$1,264.00
		'		\$1,264.00
	Panel Sub-Assy, Front Door, LH		\$228.80	\$457.60
	Front Door Rubber (LH/RH)	2 2	\$313.60	\$627.20
	Front Door Glass (LH/RH) Front Door Outer Handle (RH)	1	ψ313.00	\$378.90
	Front Door Outer Handle (LH)	1		\$378.90
	Front Door Inner Handle (LH/RH)	2	\$184.70	\$369.40
	Front Door Inner Lock	2	\$688.80	\$1,377.60
	Front Door Hinge Upper	2	\$82.30	\$164.60
	Front Door Hinge Lower	2	\$91.20	\$182.40
	Front Door Check	2	\$155.70	\$311.40
	Front Door Trimboard	2	\$725.00	\$1,450.00
	Front Door Inner Moulding	2	\$188.00	\$377.20
	Front Door Outer Moulding	2	\$188.00	\$377.20
	Front Door Handle Base	2	\$287.70	\$575.40
	Front Door Key Lock Set	1		\$428.90
	Front Door Rubber Seal	2	\$257.90	\$515.80
	Front Door Whether Strip	2	\$226.80	\$453.60
	Panel Sub-Assy, Rear Door, RH	1		\$1,258.30
	Panel Sub-Assy, Rear Door, LH	1		\$1,258.30
	Rear Door Glass (LH/RH)	2	\$313.60	\$627.20
	Rear Door Rubber (LH/RH)	2	\$228.80	\$457.60
	Rear Door Outer Handle, LH	1		\$93.90
	Rear Door Outer Handle, RH	1		\$93.90
	Rear Door Base RH/LH	2	\$93.90	\$187.90
	Rear Door Inner Lock	2	\$644.70	\$1,289.40
	Rear Door Hinge Upper RH/LH	2	\$82.30	\$164.60
	Rear Door Hinge Lower RH/LH	2	\$82.30	\$164.60
	Rear Door Check RH/LH	2	\$155.70	\$311.40
	Rear Door Trimboard RH/LH	2	\$725.00	\$725.00
	Rear Door Outer Moulding RH/LH	2	\$141.00	\$282.00
	Rear Door Inner Moulding RH/LH	2	\$141.00	\$282.00
	Rear Door Rubber Seal Outer RH/LH	2	\$257.90	\$515.80
	Rear Door Whether Strip RH/LH	2	\$176.60	\$353.20

tur

Byent

Pg 3 of 10

	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
C	Door Centre Pillar RH/LH	. 2	\$1,590.60	\$3,180.00
F	Front Door Safety Belt (LH/RH)	2	\$846.10	\$1,692.20
E	Rear Door Safety Belt (LH/RH)	2	\$838.00	\$1,676.00
F	Rear Door Safety Belt, Outer Centre (LH/RH)	2	\$526.00	\$1,052.00
- 1	Front Cushion Seat RH/LH	2	\$1,180.00	\$2,360.00
,	Front Cushion Seat Adjuster (LH)	1	4,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	\$1,450.40
- 1	Front Cushion Seat Adjuster (RH)	1		\$1,530.80
- 1	Front Cushion Seat Cushion Pad (RH)	1 1		\$526.80
- 1	Front Cushion Seat Cushion Pad (LH)	'		\$850.40
- 1	Front Cushion Seat Cushion Cover (LH/RH)		\$1,580.00	\$3,160.00
- 1	Front Cushion Seat Back Pad (LH/RH)	2	\$520.30	\$1,040.60
	•	2	1	
	Front Cushion Seat Back Cover (LH/RH)	2	\$2,940.20	\$5,880.40
	Front Cushion Seat Back Frame (LH/RH)	2	\$780.80	\$1,561.60
	Motor Assy, Power Window Regulator, RH	1		\$941.80
	Motor Assy, Power Window Regulator, LH	1		\$768.90
	Regulator Sub-Assy, Front Door Window, RH	1		\$233.70
	Regulator Sub-Assy, Front Door Window, LH	1		\$233.70
	Glass, Sub-Assy, Front Door, RH	1		\$780.00
	Glass, Sub-Assy, Front Door, LH	1		\$780.00
	Glass, Sub-Assy, Rear Door, RH	1		\$780.00
	Glass, Sub-Assy, Rear Door, LH	1		\$780.00
	Mirror Assy, Outer Rear View, RH / LH	2	\$1,390.10	\$2,780.20
	Cover, Outer Mirror, RH / LH	2	\$141.90	\$283.80
	Outer Mirror, RH / LH	2	\$212.80	\$425.60
	Window Assy, Quarter, RH	1		\$488.20
	Window Assy, Quarter, LH	1		\$168.10
	Moulding, Front Door Window Frame, Rear RH	1		\$53.70
	Moulding, Front Door Window Frame, Rear LH	1		\$53.70
	Moulding, Rear Door Window Frame, Front RH	1		\$69.20
	Moulding, Rear Door Window Frame, Front LH	1		\$69.20
	Rocker Panel Outer RH/LH	2	\$559.20	\$1,118.40
	Reinforce Sub-Assy, Rocker, Outer RH	1		\$519.80
	Reinforce Sub-Assy, Rocker, Outer LH	1		\$519.80
	Moulding Assy, Body Rocker Panel, RH	1		\$673.60
	Moulding Assy, Body Rocker Panel, LH	1		\$673.60
	Centre Rocker Panel (Garnish) RH/LH	2	\$576.00	\$1,152.00
	Front Pillar Upper Cover, RH	1		\$96.00
	Front Pillar Upper Cover, LH	1		\$96.00
	Front Windscreen Glass	1		\$1,627.30
	Front Windscreen Glass Moulding	1	#242.40	\$208.60
	Front Windscreen Glass Pillar RH/LH	2	\$343.10	\$686.20 \$784.10
	Wiper Motor Frt	1 1		\$784.10
	Arm, Front Wiper, RH	1		\$180.10
	Blade, Front Wiper, RH	1 1		\$147.90 \$180.10
	Arm, Front Wiper, LH	1 1		\$180.10
	Blade, Front Wiper, LH	1 1		\$668.32
	Wiper Top Garnish	1 1		\$183.75
	Wiper Spare Tank]		\$183.75
	Wiper Spare Tank Motor	1 1		
	Wiper Spare Tank Float (Neck)	1		\$135.00
	Fuse Box Top Cover	1 1	1	\$82.30

> BURNT

T NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Fuse Box Assy	1		\$131.80
	Front Wheel Rim RH/LH	2	\$1,570.55	\$3,141.00
	Front Wheel Hub Cap RH/LH	2	\$177.70	\$355.40
	Front Wheel Hub Bearing RH/LH	2	\$560.10	\$1,120.20
	Front Suspension Lower Arm (RH)	1		\$637.50
	Front Suspension Lower Arm (LH)	1		\$637.50
	Front Shock Absorber (LH)	1		\$401.80
	Front Shock Absorber (RH)	1		\$401.80
	Absprber Top Mounting (LH/RH)	2	\$196.20	\$392.40
	Front Drive Shaft (LH)	1		\$1,764.00
	Front Drive Shaft (RH)	1		\$1,764.00
	Rack & Pinion Assy	1		\$1,634.90
	Bar, Stabilizer	1		\$360.00
	Link Assy, Front Stabilizer, LH	1		\$199.00
	Knuckle, Steering, RH	1		\$580.80
	Knuckle, Steering, LH	1		\$580.80
	Joint Assy, Lower Ball, Front RH /LH	2	\$199.90	\$399.80
	Disc, Front	2	\$1,570.00	\$3,140.00
	Hub Sub-Assy, Front Axle, RH/LH	2	\$549.70	\$1,099.40
	End Sub-Assy, Tie Rod, RH	1		\$159.30
	End Sub-Assy, Tie Rod, LH	1		\$159.30
	Engine Under Cover	1		\$457.20
	Engine Cross Member	1		\$2,531.70
	Frt ABS Wire	1		\$455.10
	Frt ABS Sensor	1		\$222.10
	Front Chassis Member (LH)	1		\$2,035.10
	Front Chassis Member (RH)	1		\$2,035.10
	Engine Mounting (LH/RH)	2	\$386.60	\$773.20
	Engine Mtg (Front)	1		\$174.63
	Engine Mtr (Rear)	1		\$172.90
	Engine Top Cover	1		\$260.00
	Engine Room Wire	1		\$2,133.90
	Engine Room Wire Frt For Fuse Box	1		\$207.20
	Gearbox Assy	1		\$13,850.50
	Gearbox Mounting	1		\$261.00
	Engine Main Wire	1		\$6,138.00
	Brake Booster	1		\$2,771.70
	Brake Master Pump	1		\$6,378.70
	Front Brake Hose	1		\$90.70
	Front Brake ABS Sensor Only	1 1		\$450.70
	Front Brake Calipers	1		\$882.90
	Fan Belt	1		\$155.00
	Side Airbag, LH	1		\$1,479.00
	Side Airbag, RH	1		\$1,479.00
	Air Bag Assy, Driver Side Lower	1		\$1,615.00
	Air Bag Assy, Front Seat, RH	1		\$857.90
	Air Bag Assy, Front Seat, LH	1		\$857.90
	Air Bag Assy, Instrument Panel Passenger w/o Door, LH	1		\$3,277.50
	Roof Top Cover Aigbag	1		\$1,463.80
	Dashboard Air Bag Assy Passenger	1		\$3,240.20
	Air Bag Sensor	1		\$986.00
	Instrumental Panel	1		\$1,536.20

BURNT

	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
- 1	Roof Lining	1		\$2,082.
	Dashboard Assy	1		\$5,480.9
	Arm Rest Assy	1		\$1,389.9
	Computer Assy, Air Bag ECU	1		\$2,402.2
	Sensor, Air Bag, Front RH	' '		1
	Retainer, Ultrasonic Sensor, No. 1	1		\$313.5
	Sensor, Water Temperature (For E.F.I.)	1		\$49.6
1	Wire, Skid Control Sensor	1		\$118.1
- 1	Wire, Skid Control Sensor	1		\$78.8
- 1	Sensor, Speed, Front RH	1		\$78.8
- 1	Sensor, Speed, Front LH	1		\$446.5
- 1	Switch, Push Start	1		\$446.5
- 1	Computer, Engine Control	1		\$412.0
- 1	Sensor Assy, Side Air Bag, RH	1		\$2,636.1
- 1	Sensor, Air Bag, Rear RH	1		\$709.3
- 1	Sensor, Battery Voltage	1		\$567.8
- 1	Transmitter Sub-Assy, Electrical Key	1		\$256.8
- 1	Cover, Rain Sensor	1		\$447.1
- 1		1		\$500.7
- 1	Engine Front Mounting Bracket, LH	1		\$172.9
- 1	Cover, Engine Undercover Centre	1		\$448.3
- 1	Cover, Engine Under, No. 2	1		\$76.9
- 1	Cover, Engine Under, No. 2	1		\$76.90
- 1	Cover, Engine Under, Rear RH	1		\$84.90
П	Cover, Engine Under, Rear LH	1		\$84.90
1	Engine Main Wire	1		\$6,138.00
П	Wiring Front	1		\$8,450.50
П	Wiring Engine	1		\$2,133.90
1	Wiring Floor	1		\$3,380.60
L	Wire, Engine, No. 2	1		\$195.00
ı	Wire, Instrument Panel, No. 3	1		\$4,208.10
П	Vire, Front Door, RH	1		\$445.70
ı	Vire, Front Door, LH	1		\$445.70
1	Vire, Rear Door, No. 1	1		\$280.20
1	Vire, Rear Door, No. 2	1		\$280.20
	Vire, Floor	1		\$3,380.00
ı	Vire, Back Door, No. 1	1		\$246.80
1	Vire, Front Seat, RH No. 2	1		\$248.80
ı	telay, Integration No. 1	1	1	\$366.10
ı	elay, Integration No. 1	1		\$243.20
	auge Assy, Fuel Sensor, No. 2	1		\$212.20
S	witch Assy, Oil Pressure (For Engine)	1		\$63.80
	ens, Meter, No. 2	1		\$66.10
R	eflector, Combination Meter, No. 1	1		\$116.90
C	ontrol & Panel Assy, Integration	1		\$347.60
C	ontrol & Panel Sub-Assy, Integration	1		\$226.00
M	aster Switch Assy, Multiplex Network	1		\$539.50
Sv	witch Assy, Headlamp Dimmer	1		\$330.30
Sv	vitch, Headlamp Leveling	1		\$146.70
Sv	vitch, Steering Pad, RH	1		\$557.40
Sv	vitch, Steering Pad, LH	1		\$568.70
Са	able Sub-Assy, Spiral w/Sensor	1		\$953.70
Sv	vitch Assy, Stop Lamp	1		\$68.10

)BURNT

RT NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Switch Assy, Windshield Wiper	1		\$375.00
	Switch, Transmission Shift Main	1		\$138.90
	Switch, Trip	1		\$252.20
	Body Assy, Throttle	1		\$1,965.40
	Manifold Assy	1		\$875.60
	Intake Air Flow (Air Flow Sensor)	1		\$344.60
	Injector Assy, Fuel	1		\$476.10
	Actuator	1		\$881.60
	Valve Assy, EGR	1		\$685.00
	Gasket, EGR Valve	'		\$11.50
	Motor Assy, Hybrid Vehicle	'		\$4,833.00
	Generator Assy, Hybrid Vehicle	'		\$3,358.10
	Inverter Assy, w/Converter	'		\$5,390.20
	Battery Assy, HV Supply	'		\$5,544.40
	Transaxle Assy, Hybrid Vehicle	'		\$10,249.20
	Hybrid Inverter Spare Tank			\$371.30
	Hybrid Inverter Bypass Hose (Inlet)	'		\$42.60
				\$29.30
	Hybrid Inverter Bypass Hose (Outlet) Hybrid Cooling Pump Motor	'		\$432.20
		'		\$84.70
	Pole Sub-Assy, Roof Antenna	'		\$312.00
	Key Lock Antenna Rear Trunk Lid Cover	1		\$1,126.60
	Rear Trunk Lid Lock	'		\$457.90
	Rear Trunk Lid Cover Trim Board	1		\$254.40
	Rear Trunk Lid Rubber	1		\$365.20
	Rear Trunk Lid Glass (Black Color)	1		\$1,569.70
	Rear Trunk Trim Board	1		\$360.80
	Rear Trunk Outer Garnish	1		\$889.70
	Rear Trunk Hinge RH/LH	2	\$59.80	\$59.80
	Rear Trunk Lamp RH/LH	2	\$233.90	\$467.80
	Rear Trunk Lid Logo (Prius)	1		\$60.80
	Rear Trunk Lid Logo (Hybrid)	1		\$52.40
	Rear Trunk Lid Logo (Toyota Star)	1		\$52.90
	Roof Top Moulding (Centre)	1		\$950.00
	Roof Top Garnish Sub, LH	1		\$75.00
	Roof Top Garnish Sub, RH	1		\$75.00
	Cover, Assy, Tonneau	1		\$923.40
	Plate, Rear Wheel House, Front RH	1		\$57.50
	Plate, Rear Wheel House, Front LH	1		\$57.50
	Motor & Pump Assy, Rear Washer	1		\$240.80
	Motor Assy, Rear Wiper	1		\$734.60
	Link Assy, Windshield Wiper	1		\$369.00
	Arm Assy, Rear Wiper	1		\$86.40
	Blade Assy, Rear Wiper	1		\$55.00
	Jar Assy, Windshidle Washer	1		\$180.10
	Rear Bumper	1		\$458.60
	Rear Bumper Re-Inforcement	1		\$318.80
	Rear Bumper Under Cover	1		\$552.60
	Rear Bumper Side Retainer RH/LH	2	\$112.70	\$112.70
	Rear Bumper Under Side Cover (RH)	1	Ţ., <u>z.,</u> ,	\$232.00
	Rear Bumper Under Side Cover (KH)	1		\$232.00
	Incar bumper onder olde oover (E11)	'		

BURNT

10.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper Towing Cover	1		\$82.70
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Bumper Reflector RH/LH	2	\$30.50	\$61.00
	Arm Sub-Assy, Rear Bumper, RH	1		\$139.60
	Arm Sub-Assy, Rear Bumper, LH	1		\$139.60
	Retainer, Rear Bumper, Upper Side	1		\$30.70
	Retainer, Rear Bumper, Side, RH	1		\$94.80
	Retainer, Rear Bumper, Side, LH	1		\$94.80
	Seal, Rear Bumper Side, RH	1		\$148.40
	Seal, Rear Bumper Side, LH	1		\$148.40
	Tial Lamp Assy (Upper) RH/LH	2	\$557.90	\$1,115.80
	Tail Lamp Assy (Lower) RH/LH	2	\$548.40	\$1,096.80
	Tail Lamp Quarter Panel RH/LH	2	\$216.00	\$432.00
	Tail Lamp Side Cover RH/LH	2	\$256.00	\$512.00
	Rear End Panel	1	\$255.55	\$602.10
	Rear End Panel Garnish	1 1		\$165.80
	Rear Spare Tyre Panel	'		\$667.70
	Rear Spare Tyre Cushion (Fir Board Centre)	'		\$101.40
	Rear Fiber Tool Box Trim	'		\$398.00
	Rear Spare Tyre Nut	'		\$88.00
	3rd Brake Light			\$198.40
	Fiber Two Box Tray			\$398.00
	Rear Exhaust Pipe	1 1		\$1,163.40
	Rear Exhaust Pipe (Front)	1 1		\$2,966.20
	Rear Exhaust Pipe Hanger	1		\$40.70
	Rear Exhaust Pipe Insulator	1		\$314.60
	Rear Exhaust Pipe Centre Insulator	1 1		\$498.60
	Rear Fender, LH	1		\$836.70
	Rear Fender, RH	1		\$836.70
	Rear Fender Inner Panel, LH	1		\$728.00
	Rear Fender Inner Panel, RH	1		\$728.00
	Rear Fender Outer Panel, LH	1		\$486.00
	Rear Fender Outer Panel, RH	1		\$486.00
	Rear Fender Panel, Roof Side Outer, LH	1		\$311.00
	Rear Fender Panel, Roof Side Outer, RH	1		\$311.00
	Rear Fender Reinforcement, Rocker, Panel, LH	1		\$552.30
	Rear Fender Reinforcement, Rocker Panel, RH	1		\$552.30
	Rear Fender Extension, Roof Side Inner Frt,LH	1		\$265.10
	Rear Fender Extension, Roof Side Inner Frt RH	1		\$265.10
	Rear Fender Side Panel	1		\$165.00
	Rear Fender Shield (LH/RH)	2	\$134.20	\$268.40
	Rear Fender Trimboard (LH/RH)	2	\$725.00	\$1,450.00
	Rear Floor Panel Side (LH)	1		\$276.20
	Rear Floor Panel Side (RH)	1		\$276.20
	Rear Fender Top Cover (Black Color)(LH/RH)	2	\$301.10	\$602.20
	Rear Fender Air Duct	1		\$165.10
	Rear Fender Top Panel Inner RH/LH	2	\$340.20	\$680.40
	Rear Chassis Member RH/LH	2	\$1,180.80	\$2,361.60
	Rear Floor Board (LH)	1	1	\$301.00
	Rear Floow Board ((RH)	1		\$301.00
	Rear Floor Under, Cover Centre	1		\$322.00
	Rear Floor Under Cover	1	1	\$334.00

gurm

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
ear Crossmember Under Cover	1		\$353.0
Rear Floor Panel	1		\$2,850.5
Rear Windscreen Glass With Moulding	1		\$1,778.3
Rear Windscreen Glass Moulding	1		\$208.6
Smart Transmitter Key			\$447.1
Rear Tyre Rim (LH/RH)	2	\$1,570.55	\$3,141.1
lear Wheel Hub Cap (LH/RH)	2	\$1,370.33	\$354.00
Rear Wheel Bearing Ing & Hub RH/LH		\$610.20	\$1,220.40
Rear Cross Member	2	\$610.20	\$2,200.40
Rear Shock Absorber	1	\$118.60	\$2,200.40
Rear Shock Absorber Mounting	2	\$118.80	\$250.60
Rear Lower Arm	2		\$995.00
Rear Upper Arm	2	\$497.50	\$713.60
Rear Opper Arm Rear Knuckle Arm	2	\$356.80	
	2	\$810.60	\$1,621.20
Rear Coil Spring	2	\$191.40	\$382.80 \$157.60
Rear Brake ABS Sensor (Wire)	2	\$78.80	\$157.60 \$311.50
Rear Stabilizer Bar	1	0454.00	\$311.50 \$303.30
Rear Stabilizer Link RH/LH	2	\$151.60	\$303.20 \$638.40
Rear Trailing Arm RH/LH	2	\$314.20	\$628.40 \$684.40
Rear Assist Arm RH/LH	2	\$342.20	\$684.40
Rear Brake Hose RH/LH	2	\$90.70	\$181.40
Rear Brake ABS Sensor Wire RH/LH	2	\$78.80	\$157.60
Rear Brake ABS Sensor RH/LH	2	\$241.10	\$482.20
Rear Brake Caliper RH/LH	2	\$842.90	\$1,685.80
Rear Brake Disc Rotor RH/LH	2	\$416.50	\$833.00
SUB TOTAL	,		\$345,106.69
LESS 20%			\$69,021.33
DISCOUNTED TOTAL			\$276,085.35
- VP - N - Plate	2	\$25.00	\$50.00
Front/Rear No. Plate	2	\$30.00	\$50.00 \$60.00
Front/Rear No. Plate Trim Cover	1	φ30.00	\$99.00
Front No. Plate Garnish Front Windscreen Sealant	2	\$46.00	\$92.00
3. • · · · · · · · · · · · · · · · · · ·	2	\$216.00	\$432.00
Front Tyre (LH/RH)	2	\$216.00	\$432.00
Rear Tyre (LH/RH)	1	Ψ210.00	\$40.00
Rear Trunk Lid Apps Sticker	1		\$60.00
Rear Trunk Lid Comfort & Tel No. Sticker	1		\$135.70
Rear Bumper Reverse Sensor	1		\$50.00
Rear Bumper Rubber Mat	'		\$50.00
SUB TOTAL			\$1,450.70
TOTAL SPARE PARTS			\$277,536.05
_abour Charge			
			\$10,000.00
Panel Beating			¢0,000,00
Panel Beating Spray Painting Charge			\$8,000.00
X 100 (300 S			\$500.00

ART NO.

T NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Towing Charge – King Dolly			\$200.0
	Front Chassis Alignment Charge			\$400.0
	Remove/Refix Cushion & Upholstery Rear			\$150.0
	Remove/Refix Rear Windscreen Glass			\$120.0
	Remove/Refix Reverse Sensor			\$120.0
	Remove/Refix Undercarriage (RR)			\$200.0
	Remove/Refix Fuel Tank			\$150.0
	Remove/Refix Exhaust Pipe			\$150.0
	Repair Exhaust Pipe			\$120.0
	Transfer of Door			\$120.00
	Remove/Refix Auto Door Lever Assy			\$400.00
	Remove/Refix Rear Axle			\$280.00
	Repiar Gear Box			\$150.00
	Repair Rear Top/Lower Cushion Seat			\$300.00
	Remove/Refix Undercarriage (Frt)			\$200.00
	Rear Wheel Alignment			\$120.00
	Remove/Refix Radiator			\$280.00
	Remove/Refix Aircon & Refill Gas			\$150.00
	Remove/Refix Engine			\$500.00
	Remove/Refix Dashboard			\$450.00
	Remove/Refix Fuse Box			\$180.00
	Remove/Refix Front Windscreen Glass			\$120.00
	Remove/Refix Cushion & Upholstery Front			\$150.00
	Remove/Refix Steering Rack/Wheel/Dr Shaft			\$500.00
	Remove/Refix Power Steering Pump			\$450.00
	Remove/Refix Brake Master & Booster Pump			\$180.00
	Remove/Refix A/C Pump			\$120.00
	Remove/Refix Fuel Pump			\$120.00
	Repair Front Cushion Seat			\$300.00
	Remove/Refix Seat Adjuster			\$120.00
	Remove/Refix Roof Top Taxi Digital Sign			\$150.00
	Remove/Refix Roof Top Advertisement			\$150.00
	Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$550.00
	Reset Boot Lid Smart Key			\$120.00
	Diagnosis & Resetting To Erase Fault Code			\$480.00
	TOTAL LABOUR			\$27,250.00
	ESTIMATE TOTAL			\$304,786.05

NAZ LKK 221912020 1430 Plp

- valide severely burnt.
- not accommital to repair. Recommend lodge loss.
- coquest latest servicing records and book value