LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Co

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

Azlan, Syazairdina

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Date: 29 Sep 2020

Preliminary Advice

 Vehicle No
 : SMQ885U
 Accident Date
 : 18/09/2020

 Make
 : AUDI A4
 Policy No.
 : 1900166839

 Assignment Date
 : 21/09/2020
 Excess
 : \$\$550.00

Date of Inspection : 21/09/2020 Est. Duration of Repair : 6

Inspection At : PREMIUM AUTOMOBILES PTE LTD (HQ)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,863.00 (inclusive supp \$ 565.00)
-----------------------------	------	--------------------------------------

Revised Amount :S\$ 24,128.00 (inclusive supp)

 Check Items (Estimated)
 :S\$ 3,892.00

 Total
 :S\$ 28,020.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 132,000.00

 COE / PARF Rebate
 :S\$ 62,729.00

Salvage Value :S\$

Margin for Repair :S\$ 69,271.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.	
	Kindly let us have your authorisation.	

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Kindly approve on supplementary.