



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SJC3132Z KIA CERATO K3 1.6

Page No. 1-1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear boot lid / <i>00</i>		1080.00	
1	Rear boot lid lock / <i>BT</i>		99.00	
1	Rear boot lid "CERATO" emblem / <i>MC</i>		27.00	
1	Rear boot lid "K3" emblem / <i>MC</i>		45.00	
1	Rear boot lid "C&C" emblem / <i>MC</i>		40.00	
1	Rear boot lid logo badge / <i>MC</i>		27.00	
1	Rear bumper / <i>00</i>		486.00	
1	Rear bumper lower cover / <i>BR CUT</i>		270.00	
1	Rear bumper lower diffuser body kit / <i>BR</i>		630.00	
1	Rear reinforcement ? / <i>BR</i>		234.00	
1	End panel ? / <i>00</i>		234.00	
1	End panel top garnish ? / <i>BR</i>		45.00	
2	Rear bumper side reflector LH/RH 2*\$72 / <i>BR</i>		144.00	
2	Rear bumper side retainer LH/RH 2*\$27 / <i>BR</i>		54.00	
2	Rear parking sensor LHS 2 pcs @2*\$175 / <i>BR</i>		350.00	
1	Front bumper / <i>00</i>		486.00	
1	Front bumper lower skirt X		630.00	
1	Front bumper sponge ? X / <i>BR</i>		72.00	
1	Front reinforcement ? X		360.00	
2	Front bumper side retainer RH/LH @2*\$15 / <i>BR</i>		30.00	
1	Front center grille with chrome assy ? / <i>BR</i>		400.00	
1	Carplate base garnish / <i>BR</i>		40.00	
1	Front bumper top garnish X		45.00	
1	Front logo badge / <i>MC</i>		27.00	
1	Support panel X		486.00	
2	Front parking sensor center 2 pcs @2*\$175 / <i>BR</i>		350.00	
Part Items Total:			6691.00	
			-10% -669.10	
			6021.90	

TO be cont next page no. 1-2

Vehicle No. SJC3132Z KIA CERATO K3 1.6

Page No. 1-2

SPECIAL NETT ITEMS

1	Front bumper clips / MC	35.00	30
1	Front grille assy clips /	25.00	10
1	Rear bumper clips / MC	35.00	30
1	Front carplate with holder / OT	35.00	1
1	End panel sealant / MC	100.00	30
SN Items Total:		230.00	
Total Parts		6251.90	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. SJC3132Z KIA CERATO K3 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (SGD)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	800
3	To perform anti-rust treatment on affected areas	60.00	30
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	180.00	30
5	To remove and refit Front & Rear reverse sensor	200.00	60
Labour Total :		3040.00	
TOTAL (PARTS & LABOUR):		9291.90	

Steve (LKK)
83228813

WHL M/L
22/9/20, 10.15am
6 days
L/S
By AF SM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: