



Address : 1, Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)

Reg: 201828067M

VEHICLE REPAIR ESTIMATE

Insurance Company: BUDGET DIRECT ASIA

(MOTOR CLAIMS DEPARTMENT)

Address: NO 190, CLEMENCEAU AVE, #03-01

SHOPPING CENTRE, S(239924)

Telephone: 62212111

Fax:

Email: claims@budgetdirect.com.sg

Make/ Model : HYUNDAI AVANTE

Date: 21.09.2020

Chassis No : KMHD841CMKU936937

Vehicle No: SMN6304G

Date/Time of Accide 19.09.2020/ 0000

Reg date : 22.08.2019

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>cut d.</i>	1	\$ 785.80	<i>508</i>	\$ <i>✓</i> 785.80
2	FRONT BUMPER TOP BRACKET RH <i>new</i>	1	\$ 98.60		\$ <i>+</i> 98.60
3	FRONT BUMPER SIGNAL LAMP RH <i>new</i>	1	\$ 165.80		\$ <i>✓</i> 165.80
4	FRONT BUMPER RETAINER RH <i>new</i>	1	\$ 86.90		\$ <i>✓</i> 86.90
5	FRONT BUMPER AIR GUIDE RH <i>new</i>	1	\$ 125.80		\$ <i>✓</i> 125.80
6	FRONT BUMPER SIDE STRIP RH <i>new</i>	1	\$ 92.60		\$ <i>✓</i> 92.60
7	FRONT BUMPER SIDE COVER RH <i>new</i>	1	\$ 98.60		\$ <i>✓</i> 98.60
8	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 295.60		\$ <i>+</i> 295.60
9	FRONT BUMPER LOWER COVER <i>new</i>	1	\$ 202.30		\$ <i>+</i> 202.30
10	FRONT ENGINE UNDER COVER <i>new</i>	1	\$ 356.80		\$ <i>+</i> 356.80
11	FRONT BUMPER SPONGE <i>new</i>	1	\$ 225.60		\$ <i>✓</i> 225.60
12	FRONT BUMPER LOWER STIFFENER <i>new</i>	1	\$ 175.20		\$ <i>+</i> 175.20
13	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 589.50		\$ <i>+</i> 589.50
14	FRONT BUMPER RADIATOR GRILLE <i>new</i>	1	\$ 1,123.70		\$ <i>+</i> 1,123.70
15	FRONT SUPPORT PANEL <i>new</i>	1	\$ 950.80		\$ <i>+</i> 950.80
16	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 202.50		\$ <i>+</i> 202.50
17	FRONT HEADLAMP RH <i>cut</i>	1	\$ 1,756.40		\$ <i>✓</i> 1,756.40
18	FRONT HEADLAMP BRACKET RH <i>new</i>	1	\$ 98.60		\$ <i>+</i> 98.60
19	FRONT BONNET <i>new</i>	1	\$ 1,498.50		\$ <i>+</i> 1,498.50
20	FRONT FENDER RH <i>new</i>	1	\$ 985.60		\$ <i>+</i> 985.60
21	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 189.50		\$ <i>+</i> 189.50
Total List Price Cost					\$ 10,104.70

PARTS DISCOUNT 20%

\$ 8,083.76

3079.70

2463.76

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	FRONT FENDER INNER COWLING CLIPS <i>new</i>	1 SET	\$ 30.00		\$ + 30.00
2	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ ✓ 30.00
3	FRONT NUMBER PLATE WITH CASING <i>2</i>	1 SET	\$ 50.00		\$ + 50.00
4	FRONT ENGINE UNDERCOVER CLIPS <i>for</i>	1 SET	\$ 30.00		\$ + 30.00
5	FRONT ENGINE UNDERCOVER	1 SET	\$ 30.00		\$ + 30.00
Total Special Nett Items					\$ 170.00

30

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN ,STRAIGHTENED MEMBER	\$ 1,600.00
<i>300</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,200.00
<i>400</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 40 150.00
TO REMOVE / REFIT CONDENSER AND TOP UP GAS	\$ x 120.00
TO REMOVE/ REFIT WIRING CHECKS FOR HEADLAMP	\$ 30 150.00
Total Others Cost	\$ 420.00
GRAND TOTAL	
	\$ 11,473.76

770

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allan@casgarage.sg
Fax : 6509 9501

Action
H/S 22/09/20
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 3263.76
H/S: 2.6K