

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0692/2020/RT
DATE	:	24-Sep-20
WIP	:	50536

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMT 9642 D

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS.LOW GIAP JUAT,AMY(LU YEYUE,AMY)
ADDRESS	:	16B EWE BOON RD #04-06 PALMSRING CONDO SINGAPORE 259324
TELEPHONE	:	HP +65 98387710
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	190017121
VEHICLE NO	:	SJN 3384 E
MODEL CODE	:	A5 SB 2.0 TFSI S TRONIC(DESIGN)
MODEL YEAR	:	30/9/2019
ENGINE NO	:	CVK087635
CHASSIS NO	:	WAUZZZF51KA076521
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	21/09/2020
PLACE OF ACCIDENT	:	RAFFLES HOSPITAL CARPARK LEVEL 3

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJN 3384 E.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 280.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 400.00 X	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARS REMOVED. ✓		\$ 2,400.00 1000 ✓	✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. ✓		\$ 1,650.00 1100 ✓	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 4,922.00</u></u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 3384 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Repair</i>	1	\$	2,251.00 X	
2 FRONT BUMPER FIXING PARTS	1	\$	402.00 X	
3 FRONT BUMPER SECURING STRIP	2	\$	70.00 X	
4 FRONT BUMPER GRILLE LOWER CENTER	1	\$	194.00 X	
5 FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$	225.00 +	
6 FRONT BUMPER AIR GUIDE - RH	1	\$	62.00 +	
7 RADIATOR GRILLE	1	\$	2,300.00 +	
8 FRONT BUMPER ULTRASOUND SENSOR SUPPORT	2	\$	102.00 X	
9 RADIATOR GRILLE UPPER COVER	1	\$	187.00 X	
10 FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$	468.00 X	
11 FRONT BUMPER GUIDE - RH	1	\$	36.00 X	
12 FRONT FENDER - RH <i>Dented</i>	1	\$	1,048.00 ✓	838.40
13 FRONT FENDER ATTACHMENT PART	1	\$	53.00 X	
14 FRONT FENDER CLOSING ELEMENT - RH FRT	1	\$	73.00 >	58.40
15 FRONT FENDER BRACKET - RH FRT	1	\$	70.00 ?	
16 FRONT FENDER RIVET SET	1	\$	16.00 ✓	12.80
17 FRONT FENDER BRACKET - RH CENTRE	1	\$	35.00 ?	
18 FRONT FENDER BRACE - RH FRT	1	\$	117.00 >	93.60
19 FRONT FENDER DEFORMATION BRACKET - RH	1	\$	49.00 X	
20 FRONT WHEEL HOUSING LINER - RH	1	\$	272.00 X	
SUB-TOTAL SPARE PARTS	:	\$	8,030.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 3384 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	90.00	+
22 FRONT WHEEL SPOILER - RH	1	\$	73.00	✓
23 FRONT WHEEL SPOILER TRIM - RH LOWER	1	\$	36.00	✓
24 FRONT FENDER STONE CHIP GUARD - RH	1	\$	50.00	+
25 FRONT FENDER TRIM - RH UPPER	1	\$	35.00	+
26 HEADLIGHT TRIM - RH UPPER	1	\$	16.00	✓
27 LED HEADLIGHT - RH	1	\$	7,812.00	6,249.60 ✓
28 HEADLIGHT WASHER CYLINER - RH	1	\$	196.00	✓
29 FRONT NO PLATE	S/N	\$	60.00	+
30 SUNDRIES		\$	300.00	40.08
TOTAL SPARE PARTS	:	\$	16,698.00	
TOTAL LABOUR CHARGES	:	\$	4,922.00	
GRAND TOTAL	:	\$	21,620.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lim.
SURVEYED DATE : 24/09/20 ✓
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0692/2020/RT 2-Oct-20 Glory Tan 1 OF 1 SJN 3384 E A5 SB 2.0 TFSI S TRONIC(DESIG	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	Front fender chrome trim RHS <i>NEL</i>	\$ 157.00	\$ 125.60	
TOTAL		\$ 157.00	\$ 125.60	

For Premium Automobiles Pte Ltd



Adrian Ling

 Authorised Signature