

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMN2059R (Insd veh)	Model:	MERCEDES-BENZ CLA180 1.6
	SMC8315U (TP veh)		(A)
Date of Accident:	18/09/2020		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		32,737.55
Final Repair Cost	:	\$		16,680.00
Loss of Use	:	\$		11.00 days at \$60.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:Towing Fee	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		16,680.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> [] YES <input checked="" type="checkbox"/> [X] NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u>: Agreed Liability ____100____(%)				
B) For <u>GIA Registered Workshop</u>: BOLA Applicable: Yes/ No BOLA Scenario No: ____				
BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)				
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	Ryder Auto Pte Ltd	:	\$	16,680.00
2)		:	\$	
3)		:	\$	
4)		:	\$	

JOANNE LEE KHANG MIN

02 Jun
2022

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))