

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL: 6746 0674 FAX: 6841 7639

Vehicle No : SMT685P

Make: Honda Fit Hybrid 1.5 Auto

Accident Date: 13/09/2020

Spare parts

QTY	List Price	(S\$)	
1	Rear Bumper	492.60	de✓
1	Rear Bumper Retainer RH	16.90	nee✓
1	Rear Bumper Retainer LH	16.90	nee✓
1	Rear Bumper Reflector LH	48.00	X n n
1	Rear Bumper Reflector RH	48.00	X n n
1	Rear Bumper Strip Garnish	65.00	crn✓
1	Rear Boot lid inner trimboard.	422.00	crn✓
1	Rear Boot Lid	880.00	bt✓
1	Rear Boot Lid Cover	98.00	X n n
1	Rear Boot lid Weather Strip	92.30	X n n
1	Rear Boot Lock	151.70	bt✓
1	Rear Windscreen sealant	180	60 nee✓
1	Rear Camera	1041	X n n
1	Rear End Panel	320	R n
1	Rear End Panel Top Garnish	120.60	de✓
1	Rear Exhaust	430.10	R n
1	Rear Emblem Set	40.00	nee✓
1	LHS Rear Wheelhouse Shield	35.00	X n n
1	RHS Rear Wheelhouse Shield	35.00	X n n
Spare Parts Subtotal		4533.10	

2265.70

20% - 1812.56

S/N		(S\$)	
1	To respray painting include polishing and waxing on the changed body parts, repair portions where consistent to the accident	1000	600.
2	To apply undercoating on repaired and replaced panel	150	30.
3	To provide labour charges, workmanship to dismantle damaged parts, repair including cut and weld, re-align body structure and damaged consistent to the accident	1000	600.
4	To remove and refit windscreen	200	120.
5	To remove and refit reverse sensor	120	30.
6	To remove and refit inner garnishes, inner trim to assist repair	150	60.
7	To remove , refit , replace damaged lamps and check up rear electrical wiring	80	30.
Labour charges: Subtotal		<u>2700</u>	1470.

Special Nett Items

S/N		(S\$)	
1	Rear bumper clip	45	30 net ✓
2	Rear reverse sensor	350	200 net ✓
Labour charges: Subtotal		<u>395</u>	230

ESTIMATES PARTS AND LABOR GRAND TOTAL:

\$7628.10

1812.56
 1470
 230

 3512.56
 4158 2800
 4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: