



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0686/2020/NS
DATE	:	21-Sep-20
WIP	:	50163

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR YEO KHEE ENG
ADDRESS	:	BLK 614 ANG MO KIO AVENUE 4 #11-1007 SINGAPORE 560614 HP +65 96884398
TELEPHONE	:	OWN DAMAGE CLAIM 1900013358
TYPE OF CLAIM	:	SKS 8628 G
POLICY NO	:	AUDI A4 SEDAN 2.0 TFSI 8W 31/1/2019
VEHICLE NO	:	CVK 075735
MODEL CODE	:	WAUZZZF49KN006460
MODEL YEAR	:	19516KM
ENGINE NO	:	21-Sep-20
CHASSIS NO	:	JOHNNY BOO / ALLAN WU
MILEAGE	:	18-Sep-20
DATE IN	:	ANG MO KIO AVE 3(TOWARDS AMK AVE 8 AMK MRT)
ESTIMATED BY	:	
ACCIDENT DATE	:	
PLACE OF ACCIDENT	:	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 8628 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00 ✓	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 700.00 ✓ 250	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,650.00 ✓ 1000	1000
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 1,600.00 ✓ 1100	1100
5	TO TOW BACK VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 X	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,702.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8628 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
				S/NETT	
1	FRONT BUMPER <i>Repl</i>		\$	2,171.00	*
2	FRONT BUMPER FIXING PARTS <i>new</i>		\$	580.00	*
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$	70.00	*
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>		\$	194.00	*
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$	208.00	*
6	RADIATOR GRILLE <i>could</i>		\$	1,317.00	✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$	268.00	*
8	FRONT BUMPER FOAM FILLER PIECE ?		\$	123.00	?
9	FRONT BUMPER CARRIER ?		\$	795.00	?
10	FRONT BUMPER TOP COVER ?		\$	126.00	?
11	CAUTION SIGN STICKER ?	NEC	\$	14.00	?
12	AIRCON STICKER ?	NEC	\$	8.00	?
13	LOCK CARRIER BRACKET ?		\$	136.00	?
14	LOCK CARRIER BRACKET SUPPORT - LH / RH ?	2	\$	56.00	?
15	BONNET <i>Detd</i>		\$	2,763.00	✓
16	BONNET ATTACHMENT PARTS <i>new</i>		\$	408.00	*
17	BONNET LID HINGE - LH / RH <i>new</i>	2	\$	602.00	*
18	BONNET IMPACT PROTECTION - CENTRE <i>new</i>		\$	27.00	✓
19	BONNET IMPACT PROTECTION - LH <i>new</i>		\$	28.00	✓
20	BONNET IMPACT PROTECTION - RH <i>new</i>		\$	27.00	✓
SUB TOTAL SPARE PARTS			:	\$	<u><u>9,921.00</u></u>



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8628 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
				S/NETT	
21	BONNET STRIKER - LH / RH <i>3 new</i>	2	\$	100.00	<i>X</i>
22	BONNET LID LOCK	2	\$	423.00	<i>X</i>
23	BONNET BOWDEN CABLE - CENTRE <i>new</i>		\$	57.00	<i>X</i>
24	BONNET BOWDEN CABLE <i>3 new</i>		\$	57.00	<i>X</i>
25	BONNET RELEASE LEVER		\$	13.00	<i>X</i>
26	LED HEADLIGHT - LH / RH <i>RH cracked</i>	2	\$	15,386.00	<i>7693</i>
27	LIFT CYLINDER - LH / RH <i>new</i>	2	\$	416.00	<i>X</i>
28	RADIATOR AIR GUIDE - LH / RH <i>?</i>	2	\$	56.00	<i>?</i>
29	RADIATOR AIR GUIDE - LH / RH <i>?</i>	2	\$	24.00	<i>?</i>
30	RADIATOR AIR GUIDE - UPPER <i>3 new</i>		\$	16.00	<i>X</i>
31	RADIATOR AIR GUIDE - LOWER		\$	22.00	<i>X</i>
32	FRONT NO PLATE <i>Dented</i>	S/N	\$	60.00	<i>✓</i>
33	SUNDRIES <i>?</i>		\$	250.00	<i>?</i>
TOTAL SPARE PARTS			:	\$	26,801.00
TOTAL LABOUR CHARGES			:	\$	4,702.00
GRAND TOTAL			:	\$	<u>31,503.00</u>

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian
: 22/09/20
:
:
:
: Not Authorised, 05 Days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT