



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC20010173/Atd3e2 Date: 13/01/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8448U	Veh. Inspected	FBA 7100U	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023531	Excess (\$)	0.00	
Assign From		Assign Date	22/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA SUPREME X-1	c.c	111	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	5YW045000	Colour	GREY	
Odometer	200969 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90 R17	CORSA	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90 R17	CORSA	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2020	Inspection Date	23/09/2020	
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	