



**TRANS EUROKARS PTE LTD**  
**5 UBI CLOSE, SINGAPORE 408605**  
**FINALIZATION COST OF REPAIRS**



|                                                                                                                                            |                   |                                                                                                                                |           |                                                                      |                  |
|--------------------------------------------------------------------------------------------------------------------------------------------|-------------------|--------------------------------------------------------------------------------------------------------------------------------|-----------|----------------------------------------------------------------------|------------------|
| <b>LONPAC INSURANCE BHD</b><br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSE<br>Singapore 199555<br><b>ATTN :</b> MOTOR CLAIMS<br><b>FAX :</b> |                   | <b>NAME :</b> Mr Hao Yutao<br><b>ADDRESS :</b> Blk 331 Sembawang Close<br>#12-363<br>Singapore 750331<br><b>TEL :</b> 91824068 |           | <b>WIP :</b> 36853<br><b>EXCESS :</b> NIL<br><b>DATE :</b> 22-Sep-20 |                  |
| <b>VEH NO :</b>                                                                                                                            | <b>SKW3099U</b>   | <b>DATE IN :</b>                                                                                                               |           | <b>CONTACT PERSON :</b>                                              | RONALD           |
| <b>CHASSIS NO :</b>                                                                                                                        | JM6BP2HAAK1102352 | <b>MILEAGE :</b>                                                                                                               |           | <b>TYPE OF CLAIM :</b>                                               | 3RD PARTY CLAIMS |
| <b>MODEL :</b>                                                                                                                             | MAZDA3            | <b>DATE REG.:</b>                                                                                                              | 31-Jan-20 | <b>POLICY NO. :</b>                                                  |                  |

**NATURE OF WORKS**

**Parts Description**

| NO | QTY |                                          | REVISED     | PRICES      |
|----|-----|------------------------------------------|-------------|-------------|
| 1  | 1   | REAR BUMPER MBCKN-50-221BBB              | \$ 520.40   | \$ 520.40   |
| 2  | 1   | BUMPER,REAR LOWER MBCKR-50-222B          | \$ 711.20   | \$ 711.20   |
| 3  | 1   | BRACKET,BUMPER MKD53-50-251              | \$ 5.40     | \$ 5.40     |
| 4  | 1   | STAY,REAR BUMPER MBCKN-50-291A           |             | \$ 126.70   |
| 5  | 1   | RETAINER(R),REAR BUMPER MBCKN-50-2H1     |             | \$ 34.70    |
| 6  | 1   | RETAINER(L),REAR BUMPER MBCKN-50-2J1B    |             | \$ 34.70    |
| 7  | 1   | S/SPLASH RHR BUMPER MBENC-50-340         |             | \$ 60.80    |
| 8  | 1   | SHIELD(L),SPLASH MBCKN-50-350            |             | \$ 63.90    |
| 9  | 4   | FASTENER MBHN1-50-0Z1A                   |             | \$ 10.80    |
| 10 | 4   | FASTENER MBCKA-50-0Z1                    |             | \$ 9.60     |
| 11 | 1   | COVER(R),TOWING HOOK BP MBCKN-50-EK1     | \$ 9.10     | \$ 9.10     |
| 12 | 1   | COVER(L),TOWING HOOK BP MBCKN-50-EL1     |             | \$ 9.10     |
| 13 | 1   | REFLECTOR(R),REFLEX-REAR MGRF5-51-5L0A   |             | \$ 41.20    |
| 14 | 1   | REFLECTOR LHR REFLEX-GL3 MGRF5-51-5M0A   |             | \$ 41.10    |
| 15 | 1   | REINF.,REAR BUMPER BP MBCJH-50-260       |             | \$ 541.70   |
| 16 | 10  | CLIPS MBGV4-56-145                       | \$ 29.00    | \$ 29.00    |
| 17 | 6   | FASTENERS MB45A-56-146A                  | \$ 18.00    | \$ 18.00    |
| 18 | 1   | TAILGATE MBDY0-62-02XA                   | \$ 1,214.30 | \$ 1,214.30 |
| 19 | 1   | WEATHERSTRIP MBDMT-62-761                |             | \$ 154.90   |
| 20 | 7   | FASTENER MKD45-68-865                    | \$ 18.90    | \$ 18.90    |
| 21 | 4   | FASTENER MGJ21-68-885B02                 | \$ 12.00    | \$ 12.00    |
| 22 | 1   | TRIM,LIFTGATE-LOWER BP MBCKD-68-960A02   |             | \$ 267.30   |
| 23 | 1   | TRIM,LIFTGATE-UPPER BP MBCKD-68-930A02   | \$ 106.60   | \$ 106.90   |
| 24 | 1   | TRIM(R)/GATE -SIDE HB BP MBCKD-68-940A02 |             | \$ 51.70    |
| 25 | 1   | TRIM(L)/GATE -SIDE HB BP MBCKD-68-950A02 |             | \$ 51.70    |
| 26 | 1   | TAILLAMP LH MB0L6-51-160                 |             | \$ 933.70   |
| 27 | 1   | TAILLAMP RH MB0L6-51-150                 | \$ 933.70   | \$ 933.70   |
| 28 | 1   | LAMP TAILGATE LH MBCKD-51-3G0            |             | \$ 630.60   |
| 29 | 1   | LAMP TAILGATE RH MBCKD-51-3F0            | \$ 630.60   | \$ 630.60   |
| 30 | 4   | SENSOR FRT BUMPER BP MB0J8-67-UC1 64     |             | \$ 760.00   |

|                             |                      |                                                                                                        |   |                 |     |    |          |
|-----------------------------|----------------------|--------------------------------------------------------------------------------------------------------|---|-----------------|-----|----|----------|
| 31                          | SENSOR,ULTRASONIC BP | 2                                                                                                      |   | MB0J9-67-UC1    |     | \$ | 380.00   |
| 32                          | BRACKET B/SENSOR BP  | 6                                                                                                      |   | MB0J8-67-UC6    |     | \$ | 140.40   |
| 33                          | TAPE,PROTECTOR       | 3                                                                                                      |   | MBCA-50-EM1     |     | \$ | 14.10    |
| 34                          | CORD SHORT           | 1                                                                                                      | * | MBCKP-67-A20B   |     | \$ | 552.00   |
| 35                          | RETAINER SENSOR      | 1                                                                                                      |   | MB0L3-67-UC5 SY |     | \$ | 47.20    |
| 36                          | RETAINER SENSOR      | 1                                                                                                      |   | MB0L4-67-UC5 SY |     | \$ | 47.20    |
| 37                          | RETAINER SENSOR      | 1                                                                                                      |   | MB0L5-67-UC5    |     | \$ | 47.20    |
| 38                          | RETAINER SENSOR      | 1                                                                                                      |   | MB0L6-67-UC5    |     | \$ | 47.20    |
| 39                          | RETAINER SENSOR      | 1                                                                                                      |   | MB0M4-67-UC5 SY |     | \$ | 47.20    |
| 40                          | RETAINER SENSOR      | 1                                                                                                      |   | MB0M3-67-UC5 SY |     | \$ | 47.20    |
| 41                          | MONITOR,BLIND SPOT   | 2                                                                                                      |   | MB0J9-67-Y30C   |     | \$ | 3,601.40 |
| 42                          | PROTECTOR TAILGATE   | 3                                                                                                      | 6 | MBEMD-51-954    |     | \$ | 22.20    |
| 43                          | PROTECTOR TAILGATE   | 2                                                                                                      | 4 | MBEMD-51-9B5A   |     | \$ | 36.40    |
| 44                          | PROTECTOR TAILGATE   | 4                                                                                                      |   | MBEME-51-979    |     | \$ | 36.40    |
| 45                          | PROTECTOR TAILGATE   | 7                                                                                                      |   | MBEMF-51-954    |     | \$ | 102.20   |
| 46                          | PROTECTOR TAILGATE   | 1                                                                                                      | 2 | MBEME-51-954A   |     | \$ | 18.20    |
| 47                          | CLIP, TAILGATE       | 2                                                                                                      |   | MKB8A-51-SJ3    |     | \$ | 11.00    |
| 48                          | FASTENER, TAILGATE   | 7                                                                                                      |   | MKB8A-51-W24A   |     | \$ | 25.90    |
| 49                          | CLIP, TAILGATE       | 1                                                                                                      |   | MGB02-67-014    |     | \$ | 6.60     |
| 50                          | CLIP, TAILGATE       | 2                                                                                                      |   | MTK78-51-0B6    |     | \$ | 22.00    |
| 51                          | ORNAMENT HB REAR BP  | 1                                                                                                      |   | MBCKD-51-721    |     | \$ | 33.00    |
| 52                          | ORNAMENT RR HB BP    | 1                                                                                                      |   | MBCKD-51-771A   |     | \$ | 40.50    |
| 53                          | MASCOT REAR BP HB    | 1                                                                                                      |   | MBDMT-51-730F   |     | \$ | 455.60   |
| <b>SUPPLEMENTARY ITEMS:</b> |                      |                                                                                                        |   |                 |     |    |          |
| 1                           | M-HYBRID-EMBLEM      | 1                                                                                                      | * | M11-M-HYBRID    | nee | \$ | 36.70    |
| 2                           | GASKET TAILLAMP      | 2                                                                                                      |   | MBCJH-51-3H8    | nee | \$ | 39.60    |
| 3                           | CLIPS TAILGATE       | 2                                                                                                      |   | MEG21-51-146    | nee | \$ | 12.40    |
| 4                           | CLIPS SPOILER        | 2                                                                                                      |   | MBHY9-51-0A6    | nee | \$ | 20.20    |
| 5                           | GROMMET              | 4                                                                                                      |   | MK123-51-039    | nee | \$ | 11.20    |
|                             |                      |                                                                                                        |   |                 |     |    |          |
| <b>TOTAL PARTS</b>          |                      |                                                                                                        |   |                 |     | \$ | 5,845.80 |
|                             |                      |                                                                                                        |   |                 |     |    |          |
| <b>TOTAL PARTS COST</b>     |                      |                                                                                                        |   |                 |     | \$ | 5,845.80 |
|                             |                      |                                                                                                        |   |                 |     |    |          |
| <b>Labour Description</b>   |                      |                                                                                                        |   |                 |     |    |          |
|                             |                      |                                                                                                        |   |                 |     |    |          |
|                             |                      | TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. |   |                 |     | \$ | 1,320.00 |
|                             |                      | TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.                                               |   |                 |     | \$ | 1,260.00 |
|                             |                      | TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.                                    |   |                 |     | \$ | 560.00   |
|                             |                      | TO SUPPLY SEALER ON THE WINDSCREEN GLASS.                                                              |   |                 |     | \$ | 120.00   |
|                             |                      | TO TRANSFER REVERSE SENSORS.                                                                           |   |                 |     | \$ | 180.00   |

|  |              |                                                    |                           |                                  |
|--|--------------|----------------------------------------------------|---------------------------|----------------------------------|
|  |              | TO TRANSFER REVERSE CAMERA                         | \$ 180.00                 | \$ 330.00                        |
|  |              | TO TRANSFER TAILGATE MECHANISMS.                   | \$ 300.00                 | \$ 660.00                        |
|  | MZ-BR-CAVITY | TO CARRY-OUT BODY CAVITY PRESERVATION.             |                           | \$ 250.00                        |
|  | MZ-BR-ELECTR | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | \$ 120.00                 | \$ 250.00                        |
|  | MZ-BR-REPROG | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.    | \$ 150.00                 | \$ 350.00                        |
|  |              | TO SUPPLY BRILA PREMIUM COATING.                   |                           | \$ 350.00                        |
|  | MZ-BR-SUNDRI | SUNDRIES.                                          | \$ 20.00                  | \$ 100.00                        |
|  |              |                                                    | <b>TOTAL LABOUR</b>       | <b>\$ 4,210.00 \$ 7,170.00</b>   |
|  |              |                                                    | <b>TOTAL PARTS</b>        | <b>\$ 5,845.80 \$ 13,939.20</b>  |
|  |              |                                                    | <b>TOTAL</b>              | <b>\$ 10,055.80 \$ 21,109.20</b> |
|  |              |                                                    | <b>LESS EXCESS</b>        | <b>\$ - \$ -</b>                 |
|  |              |                                                    | <b>TOTAL AFTER EXCESS</b> | <b>\$ 10,055.80</b>              |
|  |              |                                                    | <b>GST 7%</b>             | <b>\$ 703.91 \$ -</b>            |
|  |              |                                                    | <b>GRAND TOTAL</b>        | <b>\$ 10,759.71 \$ -</b>         |

**REMARKS:**

**5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)**