

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 22 Sep 2020

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR NISSAN NV200 - GBH5028Y
ACCIDENT INVOLVING GBH5028Y, GBH7169K & SMG4816X ON 21/09/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear tailgate n/s -nett.	1pc	\$ 1,336.00 <i>bt</i>
2	Rear tailgate lock n/s -nett.	1pc	\$ 138.00 ?
3	Rear tailgate hinge n/s @\$105ea -nett.	2pcs	\$ 210.00 <i>Ry</i>
4	Rear tailgate inner trim n/s -nett.	1pc	\$ 342.00 x
5	NV200 -nett	1pc	\$ 88.00 <i>req</i>
6	Emblem -nett	1pc	\$ 145.60 <i>na</i>
7	Rear tailgate o/s -nett.	1pc	\$ 1,504.90 <i>bt</i>
8	Rear tailgate lock o/s -nett.	1pc	\$ 138.00 ?
9	Rear tailgate hinge o/s @\$105ea-nett.	2pcs	\$ 210.00 <i>Ry</i>
10	Rear tailgate inner trim o/s -nett.	1pc	\$ 342.00 x
11	Rear bumper- nett	1pc	\$ 700.80 <i>de</i>
12	Rear bumper retainer @\$41ea-nett	2pcs	\$ 82.00 ?
13	Rear bumper sponge -nett	1pc	\$ 145.20 ?
14	Rear end panel inner - nett	1pc	\$ 485.40 <i>Ry</i>
15	Rear end panel outer - nett	1pc	\$ 268.00 ?
16	Rear end panel top garnish-net	1pc	\$ 165.50 ?
17	Rear rubber-net	1pc	\$ 105.00 ?
18	Rear bumper reflector @\$78ea	2pcs	\$ 156.00 x
Sum Carried Forward			\$ 6,562.40

Sum Carried Forward

\$ 6,562.40

Less 10%

\$ 6,562.40

\$ (656.24)

\$ 5,906.16

19 Clips @\$4ea

10pcs \$ 40.00 *rec 30*

20 Rear sensor.

1set \$ 220.00 *200nm ✓*

21 70km

1pc \$ 15.00 *rec ✓*

22 Rear windscreen sealant

3pcs \$ 60.00 *rec ✓*

Labour Charge & Misc

To remove, repair, replace & install front
damaged parts.

} \$ 1,500.00 *700*
}

To R & R rear windscreen glass/ns/os

\$ 250.00 *180 App.*

To R & R light wiring.

\$ 60.00 *30*

To R & R sensor wiring.

\$ 80.00 *30*

To putty & spray painting.

\$ 1,200.00 *700*

Total

\$ 9,331.16

All prices quoted are subjected to 7% GST.

Taufik 1749549
'wp'
5 days - 6 days
23/9/20 & 13/10
taufik@lkkauto.com
175/70R14
Grandkanter.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: