

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

longpac  
(LKK)  
23/09/20

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST Reg No. 201629438M

21/09/2020

Owner: SKYWAY MOTOR PTE LTD

*Not Authorized*  
*11 Sep 20*  
*Returning After Paint*  
*8 days*

**ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLZ4501R**

1pc	rear tailgate	B1	\$ 1,100.90	✓
2pcs	rear tailgate hinge @\$53.60	R	\$ 107.20	X
1pc	rear tailgate "HONDA" logo	M	\$ 27.00	—
1pc	rear tailgate "VEZEL" emble	M	\$ 55.10	—
1pc	rear tailgate "HYBRID" emblem	M	\$ 68.50	—
1set	rear tailgate windscreen moulding	M	\$ 120.00	—
1pc	rear tailgate outer garnish		\$ 285.50	?
2pcs	rear tailgate RH reflector	CM	\$ 350.80	—
1pc	rear tailgate inner lock	BU	\$ 198.40	—
1pc	rear tailgate inner rubber	Dis 1Pd	\$ 135.20	50% in
1pc	rear tailgate inner garnish		\$ 320.50	?
1pc	rear tailgate inner handle garnish	su	\$ 20.70	X
1pc	rear RH taillamp	CM	\$ 460.60	—
1pc	rear bumper	Bu	\$ 986.30	—
1pc	rear bumper RH side bumper		\$ 255.20	?
2pcs	rear bumper side retainer @\$24.80	cls 1Pd	\$ 49.60	—
1pc	rear end panel	R	\$ 580.90	—
1pc	rear end panel inner garnish	CM	\$ 109.90	—
1pc	rear end panel outer sensor		\$ 195.25	?
2pcs	rear fender inner trim @\$521.90	cls CM	\$ 1,043.80	LT
1pc	rear fender RH protector	Bu	\$ 198.50	—
1pc	rear floor panel trim board	Bu	\$ 450.20	—
1pc	rear floor panel inner garnish	Mjcm	\$ 285.50	—
2pcs	front headlamp @\$1759.40	Mjcm	\$ 3,518.80	—
2pcs	front headlamp lower bracket @\$35.00	cls CM	\$ 70.00	LT ✓
2pcs	front headlamp top bracket @\$28.85		\$ 57.70	?
1pc	front centre grille base	CM	\$ 542.20	—
1pc	front centre grille chrome	CM	\$ 108.00	—
1pc	front centre grille outer garnish	CM	\$ 385.00	—
1pc	front centre grille "HONDA" logo	M	\$ 58.85	—
1pc	front centre grille bracket	su	\$ 65.20	X
1pc	front bumper	Bu	\$ 927.50	—
2pcs	front bumper side retainer @\$21.70	cls Dis	\$ 43.40	LT
1pc	front bumper grille		\$ 260.00	?
1pc	front bumper lower spoiler	su	\$ 351.00	X
20pcs	front bumper clip @\$5.00	M	\$ 100.00	—

balance c/f

\$ 13,893.20



# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST Reg No. 201629438M

21/09/2020

Owner: SKYWAY MOTOR PTE LTD

## ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLZ4501R

	balance b/f		\$ 13,893.20
1pc	front bumper reinforcement	<i>B</i> \$ 321.50	✓
2pcs	front bumper LH fog lamp garnish @\$95.58	\$ 191.16	?
1pc	front support panel	<i>R</i> \$ 676.20	X
		\$ 15,082.06	
	less 20%	\$ 3,016.41	
		\$ 12,065.65	
1set	rear reverse sensor	<i>Red</i> s.nett \$ 280.00	<i>2001R</i>
1set	front / rear number plate & casing	<i>Red</i> s.nett \$ 100.00	<i>905R</i>
	remove & refix rear windscreen glass	\$ 120.00	✓
	wiring	\$ 120.00	<i>401</i>
	tuffkote	\$ 150.00	<i>601</i>
	sealant	\$ 120.00	<i>301</i>
	spray painting	\$ 1,800.00	<i>11001</i>
	labour charges	\$ 1,600.00	<i>10001</i>
	Total	\$ 16,355.65	

