



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SFQ1878S  
Date of Accident : 18 September 2020

Mr Wong Kam Weng(Wang Jinrong)

Date : 21 September 2020

per: Lkh - Marcus

23/09/2020 C/300h

Estimate To Repair SGU5996A - Mercedes Benz GLA180 URBAN EDITION AUTO  
Chassis No : WDC1569422J667162

| S/No | Quantity | Description                                                                                                             | Amount        |
|------|----------|-------------------------------------------------------------------------------------------------------------------------|---------------|
|      |          | <b>NETT ITEMS</b>                                                                                                       |               |
| 01   | 1 pc     | front bumper <i>Deepcut</i>                                                                                             | \$ 1,250.00 ✓ |
| 02   | 1 pc     | front bumper reinforcement <i>11</i>                                                                                    | \$ 310.00 X   |
| 03   | 1 pc     | front bumper lower grille <i>Deepcut</i>                                                                                | \$ 138.00 ✓   |
| 04   | 1 pc     | o/s front bumper fog lamp <i>11</i>                                                                                     | \$ 245.00 X   |
| 05   | 1 pc     | o/s front bumper fog lamp cover <i>11</i>                                                                               | \$ 465.00 X   |
| 06   | 1 pc     | o/s headlamp <i>11</i>                                                                                                  | \$ 2,380.00 X |
|      |          |                                                                                                                         | \$ 4,788.00   |
|      |          | Less 10 %                                                                                                               | \$ 478.80     |
|      |          |                                                                                                                         | \$ 4,309.20   |
|      |          | <b>LABOUR &amp; MISC. CHARGES</b>                                                                                       |               |
| 01   |          | To check electrical lighting concerned.                                                                                 | \$ 80.00 20   |
| 02   |          | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 450.00 200 |
| 03   |          | Putty and spray painting of the affected portion.                                                                       | \$ 450.00 300 |
|      |          |                                                                                                                         | \$ 980.00     |
|      |          | Total                                                                                                                   | \$ 5,289.20   |

*not Audited  
Lkh  
who phd Schumparty.  
2 days. P/PB  
23/9/20*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: