



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

QUOTATION

Company Reg No 200608327M
GST Reg No MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000				/MOEY HON MENG (MEI HANMING)			
				Cust No/Name			
				Reg No/Reg Date	SLT9102H / 16/11/2017		
				Date In/Mileage	25/09/2020/ 0		
				Chassis/Package	VF73ABHZTHJ767307 /CC17S5		
				Engine No	10JBHD3086899		
				Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML		
				Colour/Trim	EBM LAZULI BLUE / IXF YATAGO GREY		
							
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
FAX00001	Credit	23/09/2020/ 15:05	Bod	442 / CocoLu	15670	0	
Description of Goods / Services					Qty	Unit Price	Disc% Amount
E PNT88000							1000 1500.00
RENEW REAR BUMPER, TAILGATE, TAILGATE LOWER PANEL, REPAIR REAR END PANEL							60.00
E PNT88000							240.00
REMOVE & INSTALL PARKING SENSOR							80.00
E PNT88000							40.00
REMOVE & INSTALL TAILGATE GLASS							160 200.00
M SUNDRY							1140 1520.00
APPLY SEALANT FOR REAR WINDSCREEN							50.00
M SUNDRY							225.00
C&C LOGO							20.00
E PNT88000							50.00
REMOVE & INSTALL TAILGATE TRIMS							225.00
E PNT98000							20.00
SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, TAILGATE TAILGATE LOWER PANEL							50.00
A 54900099							225.00
CHECK WIRING & ELECTRICAL SYSTEM							20.00
A 10028901							50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							50.00
M SUNDRY							50.00
Sundry							50.00
M SUNDRY							50.00
REAR NUMBER PLATE WITH FRAME <i>cm</i>							50.00
M REAR BUMPER <i>de</i>					1.00	1109.00	20.00 887.20
M BUMPER BRACKET <i>?</i>					1.00	335.00	20.00 268.00
M BUMPER SKIRT <i>de</i>					1.00	367.00	20.00 293.60
M BRACKET SET <i>?</i>					1.00	137.00	20.00 109.60
M BRACKET SET LAT <i>?</i>					1.00	137.00	20.00 109.60
M BUMPER BRACKET <i>?</i>					1.00	331.00	20.00 264.80
M STIFFENER LH <i>?</i>					1.00	85.00	20.00 68.00
M STIFFENER RH <i>?</i>					1.00	85.00	20.00 68.00

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

QUOTATION

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #08-16
AIG BUILDING
SINGAPORE 079120
Contact No 6419 1000

Owner Name & Vehicle Info

Cust No/Name /MOEY HON MENG (MEI HANMING)
Reg No/Reg Date SLT9102H / 16/11/2017
Date In/Mileage 25/09/2020/ 0
Chassis/Package VF73ABHZTHJ767307 /CC17S5
Engine No 10JBHD3086899
Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML
Colour/Trim EBM LAZULI BLUE / IXF YATAGO GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	23/09/2020/ 15:05	Bod	442 / CocoLu	15670	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M ECU ?	1.00	496.00	20.00	396.80
M BUMPER BRACKET	1.00	89.00	20.00	71.20
M LOW RR PAN FIX	1.00	168.00	20.00	134.40
M WHL OPEN MECH ?	1.00	355.00	20.00	284.00
M TAILGATE de	1.00	2667.00	20.00	2133.60
M TLGT EXT PANEL de	1.00	613.00	20.00	490.40
M TLGATE MOULDING de	1.00	266.00	20.00	212.80
M WEATHERSTRIP ?	1.00	179.00	20.00	143.20
M TAILGATE MODULE ?	1.00	435.00	20.00	348.00
M LOWER TRIM ?	1.00	455.00	20.00	364.00
M TAILGATE FIX	1.00	362.00	20.00	289.60
M BADGE	1.00	66.00	20.00	52.80
M BADGE	1.00	66.00	20.00	52.80
M BADGE	1.00	72.00	20.00	57.60
M TAILGATE LOCK ?	1.00	138.00	20.00	110.40
M TAIL-LIGHT RH COMPLEMENTAIRE	1.00	217.00	20.00	173.60
P SENSOR ?	2.00	189.00	20.00	302.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Ramu - Hp 9001068SURVEYOR SIGNATURE: [Signature]DATE: 24/09/2020 @ 1630REMARKS: 5 daysREVERT / EXCESS: TBAResurvey before paint

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	7,686.40	Nett	11,671.40
Labour	3,795.00	7% GST on	817.00
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	12,488.40
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	190.00	Total Due	12,488.40
Total (w/o GST)	11,671.40		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.