


MBM WHEELPOWER PTE LTD



Your Ref:

Our Ref: SLA728L

To: AIG

CC

Fax

Date: 23/9/2020

From: Eryx Tan

Fax: 64525333

Contact: 81387188

Make / Model: MERCEDES C200 AMG

Chassis No.: 27492030509996

Engine No.: 26491530058106

Year of Make: 2016

Accident Date: 21/9/2020

ESTIMATE FOR VEHICLE NO. : SLA728L

	<u>DESCRIPTION</u>	<u>PART NO.</u>	<u>QTY</u>	<u>List Price</u>
1	FRONT BUMPER		1	\$ 1,850.00
2	FRONT BUMPER LOWER GRILLE		1	\$ 165.00
3	BUMPER LOWER CHROME TRIM CENTRE		1	\$ 320.00
	BUMPER LOWER CHROME TRIM LH		1	\$ 185.00
	BUMPER LOWER CHROME TRIM RH		1	\$ 185.00
4	BUMPER LOWER MOUNTING CONSOLE		1	\$ 265.00
5	BUMPER SIDE RETAINER LH		1	\$ 95.00
6	BUMPER SIDE RETAINER RH		1	\$ 95.00
7	RADIATOR GRILLE CHROME		1	\$ 426.00
8	RADIATOR GRILLE BASE		1	\$ 235.00
9	GRILLE EMBLEM		1	\$ 105.00
10	HEADLAMP LH		1	\$ 3,650.00
11	HEADLAMP RH		1	\$ 3,650.00
12	FRONT DISTANT SENSORS		2	\$ 500.00
	FRONT REINFORCEMENT		1	\$ 480.00
	FRONT NUMBER PLATE BASE		1	\$ 155.00
	FRONT BUMPER SPONGE		1	\$ 190.00

Parts List Total:	\$	12,551.00
Less 10% :	\$	1,255.10
	\$	11,295.90

SPECIAL NETT

NUMBER PLATE W/ HOLDER	\$	50.00
------------------------	----	-------

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS.	\$	600.00
TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	\$	120.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	60.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	600.00

Total:	\$	12,125.90
7% GST:	\$	848.81
Grand Total:	\$	12,974.71