

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0271/20

DATE : 21-SEP-2020

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299195
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : MR TAN YI RYH
ADDRESS : 3 CROWHURST DRIVE

S(557882)
TELEPHONE NO : 93885245/85775890

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1900018465-01
VEHICLE NO : SMH9617R
MODEL CODE : BOTARCZB17EWA----K19
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019
ENGINE NO : HR16939908C
CHASSIS NO : MNTBBAB1720034598
MILEAGE : 29549 KM
DATE IN : 21/09/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 21/09/2020

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

- 9645 0084 elmer@fanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH9617R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR RR END PANEL & RH RR FENDR RENEW REAR BUMPER	1170.00	390
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	750.00	250
3	ZZ/003	REMOVE AND INSTALL REVERSE SENSOR	55.00	/
4	ZZ/004	REMOVE AND INSTALL BOTH RR COMB LAMP	48.00	/
TOTAL LABOUR CHARGES			2023.00	743

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH9617R

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	SUNDRIES / <i>McC</i>	NPN			50.00 <i>20</i>
2	STAY RR BMPR RH <i>X</i> NN	85212-EE530	52.00		
3	ABSORBER ENERGY RR BUMPER <i>X</i> NN	85090-3SN5A	78.00		
4	RH REFLECTOR RR BUMPER <i>X</i> NN	26565-5C000	61.90		
5	RH SIDE BRACKET RR BUMPER / <i>McC</i>	85226-3ST1A	39.80		
6	CLIP RR BUMPER @ SGD \$ 1.40 EACH / <i>McC</i>	01553-09321	8.40		
7	REAR BUMPER / <i>De</i>	85022-3ST4H	679.90		
SUB TOTAL			920.00	0.00	50.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			184.00	0.00	0.00
GRAND TOTAL			736.00	0.00	50.00
OVERALL TOTAL			786.00		

602.48

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMH9617R

TOTAL LABOUR CHARGES	2023.00	
TOTAL SPARE PARTS CHARGES	786.00	
GRAND TOTAL	2809.00 *	1345.48

* All charges do2 not include GST.

Guo Qiang @ 1kk auto. com.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Guo Qiang - 8288 0282

25/9/2020

before paint photos.

3 Days.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.