# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #07-16

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Rparthiban, Theerthan Date: 24 Sep 2020 Attn:

## **Preliminary Advice**

Vehicle No : SME2218X Accident Date : 23/09/2020 Make : AUDI A4 Policy No. : 1800111412 : 24/09/2020 : S\$0.00 Assignment Date **Excess** Est. Duration of Repair Date of Inspection : 23/09/2020 : 6

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,384.00
Revised Amount	:S\$	6,598.00
Check Items (Estimated)	:S\$	531.00
Total	:S\$	7,129.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$
D A '	0.0

Pre-Accident Value 123,000.00 :S\$ COE / PARF Rebate :S\$ 54,688.00

Salvage Value :S\$

Margin for Repair :S\$ 68,312.00

#### Remarks

( )	X	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(		)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(		)	Other comments: