

E M SOLUTION PTE LID

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

05.10.2020

Yezi Trading

Not Noted
11pm & 1700h
Delivery After Paint 3 days

REPAIR ESTIMATE FOR TOYOTA HIACE - GBF 5186 J

1 pc	LH sliding door	<i>At Way</i>	1,688.60	✓
1 pc	LH sliding door rubber	<i>Sm</i>	406.10	✓
1 pc	LH sliding door outer handle	<i>Sm</i>	106.20	✓
1 pc	LH sliding door lock	<i>It</i>	269.60	✓
1 pc	LH sliding door inner trim	<i>Sm</i>	356.20	✓
			2,826.70	
Less 25%			706.68	
			2,120.03	
1)	Check electrical wirings		60.00	<i>15/-</i>
2)	Repair accident damages and renew above parts		580.00	<i>400/-</i>
3)	Spray paint on affected portions.		580.00	<i>400/-</i>
4)	Transfer RH door mechanisms.		100.00	<i>60/-</i>
5)	Rust proofing on affected portions.		50.00	<i>30/-</i>
			<u>\$ 3,490.03</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: