

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 201311675Z

JESSIE CATERING PTE LTD
NO 3015 BEDOK NORTH STREET 5
#04-09 SHIMEI EAST KITCHEN
SINGAPORE 486350
TEL : 62464644 (Michelle) FAX : 62464544
PH : 96950827(BOSS JIMMY)
ATTN :

ESTIMATE BILL

Number : EB00005534
Date : 24/09/2020
Case No : AD00011322
Vehicle No : GBD8959L
Chassis: JTFHT02P800162244
Year of Mfr 2015
Policy No
Model : TOYOTA HIACE 3.0
M

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER	1.0	541.20	25	405.90
2	FRONT BUMPER RETAINER RH	1.0	142.80	25	107.10
3	HEADLAMP RH	1.0	744.00	25	558.00
4	FRONT CORNER PANEL RH	1.0	268.40	25	201.30
5	FRONT DOOR RH	1.0	1,887.10	25	1,415.33
6	FRONT DOOR HINGE TOP RH	1.0	110.00	25	82.50
7	FRONT DOOR HINGE BOTTOM RH	1.0	110.00	25	82.50
8	FRONT DOOR PILLAR RH	1.0	434.20	25	325.65
9	FRONT DOOR RUBBER RH	1.0	230.10	25	172.58
10	FRONT STEP PANEL GARNISH RH	1.0	161.90	25	121.43
11	FRONT STEPPANEL RH	1.0	54.40	25	40.80
12	FRONT DOOR INNER LOCK RH	1.0	578.00	25	433.50
13	FRONT GRILLE TOP	1.0	568.60	25	426.45
14	FRONT GRILLE BOTTOM	1.0	221.70	25	166.28
15	FRONT BUMPER LOWER GRILLE	1.0	178.10	25	133.58
16	FRONT DOOR POWER WINDOW REGULATOR RH	1.0	704.80	25	528.60
17	FRONT DOOR POWER WINDOW REGULATOR MOTOR RH	1.0	704.80	25	528.60
List Price - Parts Sub Total					5,730.10
18	FRONT DOOR COMPANY DETAIL LOGO RH	1.0	30.00	0	30.00
19	FRONT FLOOR BOARD PANEL RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					30.00
Parts Total					5,760.10
20	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
21	SPRAY PAINT ON THE AFFECTED AREAS	1.0	700.00	0	700.00
22	ANTI-RUST COATING	1.0	150.00	0	150.00
23	WIRING	1.0	40.00	0	40.00
24	TO REMOVE & REFIT DASHBOARD	1.0	250.00	0	250.00
25	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
Labour 1 Sub Total					2,220.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 201311675Z

JESSIE CATERING PTE LTD
NO 3015 BEDOK NORTH STREET 5
#04-09 SHIMEI EAST KITCHEN
SINGAPORE 486350
TEL : 62464644 (Michelle) FAX : 62464544
PH : 96950827(BOSS JIMMY)
ATTN :

ESTIMATE BILL

Number : EB00005534
Date : 24/09/2020
Case No : AD00011322
Vehicle No : GBD8959L
Chassis: JTFHT02P800162244
Year of Mfr 2015
Policy No
Model : TOYOTA HIACE 3.0
M

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : EIGHT THOUSAND FIVE HUNDRED THIRTY-EIGHT AND CENTS SEVENTY-ONE ONLY			Less Excess		0.00
			SUBTOTAL		7,980.10
			GST 7.00%		558.61
			TOTAL		8,538.71

Date of accident : 23/09/2020 01:40 PM. Place : LITTLE ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE