

Ude-khrodne

FASTTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6
01-48 S'PORE 417883

Not Authorised
Nbr
a/s @ 4550
S day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VEHICLE NO:GBE 1235H

1PC	TAILGATE	Body PD	\$1,645.10	—
1PC	TAILGATE DYNA STICKER	ner	\$45.50	—
1PC	TAILGATE LOWER MEMBER	Bent	\$545.10	—
1PC	TAILGATE LOCK LATCH O/S	n	\$119.30	X
1PC	TAILGATE 1500kg STICKER	17	\$30.00	X
2PCS	TAILLAMPS @\$ 285.30	One	\$570.60	—
2PCS	TAILLAMP PANELS @ \$119.30	0/5 Bent	\$238.60	10c
1PC	TAILGATE LOWER 'L' PANEL O/S	Bent	\$68.50	—
1PC	TAILGATE LOWER 'L' PANEL RUBBER O/S	M.S	\$62.30	—
2PCS	TAILGATE LOWER MEMBER REFLECTORS @\$65.	One	\$130.00	—
1PC	REAR EXHAUST PIPE	20/Bent	\$585.20	—
1PC	REAR EXHAUST PIPE MONTING	17	\$112.00	X
1PC	REAR CENTRE CROSS MEMBER	20/Bent 680-10	\$845.20	—
1PC	REAR SPARE TYRE CHAIN & BRACKET	Dange/17m	\$392.50	—
1PC	REAR SPARE TYRE 'L' BRACKET	Bent	\$85.00	—
1PC	REAR LICENCE PLATE BRACKET	Bent	\$119.50	—
			\$5,594.40	

257

S.NETT

1PC	TAILGATE 70KM/hr STICKER	ner	\$20.00	10
1PC	TAILGATE 13 PAX STICKER	ner	\$20.00	10
1SET	REAR REVERSE SENSOR	short	\$380.00	200
1PC	REAR LICENCE PLATE	Bent	\$40.00	14
1PC	REAR TAILLAMP REFLECTOR O/S	17	\$50.00	X

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO SPRAY RUST PROOFING	\$120.00	50
TO DISMANTLE & REPLACING REAR EXHAUST	\$100.00	60
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,000.00	800
TO PUTTY & SPRAY PAINTING	\$1,500.00	700
TOTAL	\$8,984.40	

p-5018.70
257/10
p-376402
S.wf-234.00
L-1090.00
5088.02