Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18 Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No. : 200616038C GST Registration No. : 200616038C

Our Ref:

GBB 5096 G

Your ref:

SHC 1771 R

28 September 2020

INDIA INTERNATIONAL INSURANCE PTE LTD

BY EMAIL motorclaim@iii.com.sg ONLY

64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711

Attn: Motor Claims Department

Dear Sir/Madam,

DATE OF ACCIDENT: 27 Sept 2020

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by TING SENG CEREMONIAL PRODUCTS to notify you of a road traffic accident on 27 Sept 2020 at about 13:25 HRS along CTE/SLE AFTER MOULMEIN ROAD EXIT involving our client's vehicle GBB 5096 G & SHC 1771 R driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,

N-51 AUTOMOTIVE PTE LTD