

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/09/2020	Cust No/Name	/CHUA DONG YANG
	Reg No/Reg Date	SMD8103J / 06/09/2018
	Date In/Mileage	29/09/2020/ 26907
	Chassis/Package	MMBSTA13AJH003163 /CS5P
	Engine No	3A92UHG6508
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/10/2020/ 12:48	BLC	881 / Jojo Cheng	57828			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2250.00
RENEW FRONT BUMPER, FRONT AIRDAM, BONNET, FRONT SUPPORT PANEL, RHF FENDER, RH SIDE SKIRT, RHF WHEEL HOUSING, REPAIR LHF FENDER, RHF DOOR, RH ROCKER PANEL, RH A-PILLAR								
E PNT88000								100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
E PNT88000								120.00
REMOVE & INSTALL FRONT AIRDAM & SIDE AIRDAM								
E PNT98000								3500.00
SPRAY PAINT FRONT BUMPER, FRONT AIRDAM, FRONT SUPPORT PANEL, BONNET RHF & LHF FENDER, RHF DOOR, RH SIDE SKIRT, RH A-PILLAR, RH ROCKER PANEL, RH WHEEL HOUSING								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
A 54900099								225.00
RENEW FRONT UNDER CARRIAGE								
M SUNDRY								40.00
APPLY SEALANT FOR DAMAGED PORTION								
A 54900099								225.00
RENEW FRONT CROSSMEMBER -SUPP								
E PNT88000								500.00
ADDITIONAL JOB - STRAIGHTEN FRONT CHASSIS - FLOOR BENCH -SUPP								
E PNT88000								225.00
ADDITIONAL JOB - REPAIR RH CHASSIS MEMBER -SUPP								
S TYRESALES2								250.00
SUPPLY RH FRONT TYRE								
S SPECIALISTJOB								30.00
LABOUR TO TRANSFER RHF SPORT RIM WITH VALVE SUPPLY								

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/09/2020	Cust No/Name	/CHUA DONG YANG
	Reg No/Reg Date	SMD8103J / 06/09/2018
	Date In/Mileage	29/09/2020/ 26907
	Chassis/Package	MMBSTA13AJH003163 /CS5P
	Engine No	3A92UHG6508
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	19/10/2020/ 12:48	BLC	881 / Jojo Cheng	57828	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
X EXC						-800.00
EXCESS FOR OWN DAMAGE CLAIM						
X	WHEELHOUSE,FR INR RH		1.00	347.00	23.00	267.19
X	FACE,FR BUMPER		1.00	703.00	23.00	541.31
X	GRILLE,FR UNDER		1.00	165.00	23.00	127.05
X	GARNISH,FR BUMPER,RH		1.00	127.00	23.00	97.79
X	HOOD		1.00	734.00	23.00	565.18
X	INSULATOR,HOOD		1.00	177.00	23.00	136.29
X	FENDER,FR RH		1.00	497.00	23.00	382.69
X	SHIELD,FR WHEELHOUSE,RH		1.00	98.00	23.00	75.46
X	PANEL ASSY,FR END		1.00	1055.00	23.00	812.35
X	MOULDING,WINDSHIELD		1.00	100.00	23.00	77.00
X	STOPPER,WINDSHIELD GLASS		2.00	3.00	23.00	4.62
X	SPACER,WINDSHIELD		2.00	6.00	23.00	9.24
X	SPACER,QTR WINDOW		3.00	8.00	23.00	18.48
X	BODY KIT, ATTRAGE, T69		1.00	1643.00	00.00	1643.00
X	HEADLAMP ASSY,RH		1.00	660.00	23.00	508.20
X	HEADLAMP ASSY,LH		1.00	660.00	23.00	508.20
X	HUB ASSY,FR WHEEL		1.00	*240.00	23.00	184.80
X	BEARING,FR WHEEL HUB		1.00	121.00	23.00	93.17
X	ARM ASSY,FR SUSP,LWR RH		1.00	337.00	23.00	259.49
X	STRUT,FR SUSP		1.00	373.00	23.00	287.21
X	BEARING,FR SUSP STRUT		1.00	9.00	23.00	6.93
X	WHEEL,DISC		1.00	687.00	23.00	528.99
X	CROSSMEMBER,FR AXLE,NO.1		1.00	864.00	23.00	665.28
X	LINK KIT,F/SUSP STABILIZER		1.00	27.00	23.00	20.79
X	STOPPER,FR SUSP STRUT		1.00	27.00	23.00	20.79
X	KNUCKLE,RH		1.00	365.00	23.00	281.05
X	SNAP RING,FR WHEEL HUB		1.00	8.00	23.00	6.16
X	FRAME,FR DECK,UPR OTR RH		1.00	511.00	23.00	393.47
X	CABLE,HOOD LOCK RELEASE		1.00	30.00	23.00	23.10
X	COVER,HEADLAMP SUPT PANEL		1.00	62.00	23.00	47.74
X	TANK,WINDSHIELD WASHER		1.00	74.00	23.00	56.98

Pro Forma

215.00

* Price Change.

SUPP

* Price Change.

PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/09/2020	Cust No/Name	/CHUA DONG YANG
	Reg No/Reg Date	SMD8103J / 06/09/2018
	Date In/Mileage	29/09/2020/ 26907
	Chassis/Package	MMBSTA13AJH003163 /CS5P
	Engine No	3A92UHG6508
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 12:48	BLC	881 / Jojo Cheng	57828

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X MOTOR,WINDSHIELD WASHER	1.00	30.00	23.00	23.10
X CLIP,HOOD LOCKING - <i>Supp</i>	1.00	4.00	23.00	3.08
Z TEXT AIG OD CLAIM DOA: 28/09/2020 SURVEYOR: RASUL LKK 29/09/2020				
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	8,676.18	Nett	15,611.18
Labour	7,415.00	7% GST on	15611.18
Standard Menu	0.00		
Specialist Job	280.00	Total Payable	16,703.96
Diagnostics Job	0.00		
Sundry/Others	-760.00		
Total(w/o GST)	15,611.18		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : AIG ASIA PACIFIC INSURANCE PTE LTD

REGISTRATION NO : SMD8103J

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>LABOUR</u>					
1	RENEW FRONT CROSSMEMBER	1.00	225.00	0.00	225.00
2	STRAIGHTEN FRONT CHASSIS - FLOOR BENCH	1.00	500.00	0.00	500.00
3	REPAIR RH CHASSIS MEMBER	1.00	225.00	0.00	225.00
<u>PARTS</u>					
1	CROSSMEMBER, FR AXLE, NO1	1.00	864.00	23.00	665.28
2	LINK KIT, F/ SUSP STABILIZER	1.00	27.00	23.00	20.79
3	STOPPER, FR SUSP STRUT	1.00	27.00	23.00	20.79
4	KNUCKLE, RH	1.00	365.00	23.00	281.05
5	SNAP RING, FR WHEEL HUB	1.00	8.00	23.00	6.16
6	FRAME, FR DECK, UPR OTR RH	1.00	511.00	23.00	393.47
7	CABLE, HOOD LOCK RELEASE	1.00	30.00	23.00	23.10
8	COVER, HEADLAMP SUPT PANEL	1.00	62.00	23.00	47.74
9	CLIP, HOOD LOCKING	1.00	4.00	23.00	3.08
Total					2,411.46
7 % GST					168.80
Grand Total					<u>2,580.26</u>

Thank You.

Yours faithfully,

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

(ADDITIONAL PARTS CHANGE)

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT	9/10	ppp
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

SURVEYOR: Rasul

Work Order: R001207
License: SMD8103J
Technician: ALVIN (108)
Mileage: 29987
Date: 14.10.20 8:31

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°38'	-0°38'	-0°40' 0°50'
3°58'	3°52'	3°15' 4°45'
0°01'	-0°13**	-0°07' 0°07'
13°02'	13°14**	10°05' 13°05'
12°24'	12°36'	9°25' 13°55'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°11'	-0°11'	-0°40' 0°50'
4°30'	4°29'	3°15' 4°45'
0°00'	0°04'	-0°07' 0°07'
12°07'	12°06'	10°05' 13°05'
11°56'	11°55'	9°25' 13°55'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°27'	-0°27'	-0°30' 0°30'
-0°32**	-0°37**	-0°30' 0°30'
0°55'	1°08'	
0°01'	-0°09'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°51'	-0°51'	-1°45' -0°15'
0°11'	0°10'	-0°01' 0°13'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°13'	-1°13'	-1°45' -0°15'
0°00'	-0°01'	-0°01' 0°13'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°23'	0°22'	-0°30' 0°30'
0°10'	0°10'	-0°02' 0°26'
0°05'	0°06'	

SM B1035

After using MUT for unit to Base all the good
to do Done

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	A13A 2018MY

2020.10.13

All DTCs

2020.10.13

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	MPI/GDI/DIESEL	KOSS_99880010		No DTCs		
	AT/CVT/A-MT/TC-SST	KOSS_99880010		No DTCs		
	4WS/Electric Power Steering	KOSS_99880010		No DTCs		
	ABS/ASC/ASTC/WSS	KOSS_99880010		No DTCs		
	SRS-AIR BAG	KOSS_99880010		No DTCs		
	Air Conditioner	KOSS_99880010		No DTCs		
	ETACS	KOSS_99880010		No DTCs		
	Meter	KOSS_99880010		No DTCs		
	Steering Angle Sensor	KOSS_99880010		Non-target System		
	KOS/OSS/IMMO/Keyless (with KOS)	KOSS_99880010	B1A11	KOS key2 low battery		Active

SMD8103J

Before using MUT-32x Ver2 unit to check all 528

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	A13A 2018MY

2020.10.13

All DTCs

2020.10.13

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition		
	MPI/GDI/DIESEL	KOSS_99880010		No DTCs				
	AT/CVT/A-MT/TC-SST	KOSS_99880010		No DTCs				
	4WS/Electric Power Steering	KOSS_99880010		No DTCs				
	ABS/ASC/ASTC/WSS	KOSS_99880010	C1200	FR wheel speed sensor		Stored		
	SRS-AIR BAG	KOSS_99880010		No DTCs				
	Air Conditioner	KOSS_99880010		No DTCs				
	ETACS	KOSS_99880010		No DTCs				
	Meter	KOSS_99880010		No DTCs				
	Steering Angle Sensor	KOSS_99880010		Non-target System				
	KOS/OSS/IMMO/Keyless (with KOS)	KOSS_99880010	B1A11	KOS key2 low battery		Active		