

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMG4114M
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00361665861
Year of Manufacture : 2018

Estimation No. : E20090021
Date : 28/09/2020

No.	Description	Qty	U/P	Amt
Section: Remark				
1	3rd party claim against YN3397R - AIG Asia Pacific Insurance Pte Ltd DOA: 27/09/2020	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Parts

2	903007061R - Rear windscreen / BR	1.00	699.78	699.78
3	287901560R - Wiper blade / CRV	1.00	57.00	57.00
4	265503368R - Taillight, Tailgate RH / CRV	1.00	548.88	548.88
5	850221774R - Bumper, rear X R	1.00	1,152.96	1,152.96
6	756100714R - Bumper beam, rear X Svc	1.00	670.65	670.65
7	901523953R - Tailgate cover X R	1.00	749.28	749.28
8	908895927R - Emblem / NEC	1.00	151.20	151.20
9	908923255R - Lettering "SCENIC" / NEC	1.00	138.10	138.10
10	908924456R - Lettering "RENAULT" / NEC	1.00	138.10	138.10
11	901007869R - Tailgate assy X Svc	1.00	2,247.60	2,247.60

Amt S\$ 6,553.55
Discount (10.00%) S\$ 655.35
Subtotal S\$ 5,898.20

Section: Special nett

12	Tinted film / NEC	1.00	350.00	350.00 4200
13	PHC decals / NEC	1.00	20.00	20.00 ✓

Amt S\$ 370.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 370.00

Section: Labour

14	Labour for replacing damaged parts as per above.	1.00	1,000.00	1,000.00
----	--	------	----------	----------

400 ~~3000~~
Continue on next page...

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMG4114M
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00361665861
Year of Manufacture : 2018

Estimation No. : E20090021
Date : 28/09/2020

No.	Description	Qty	U/P	Amt
15	To check tailgate water seepage X	1.00	80.00	80.00
16	Labour for putty and spray paint on rear bumper and tailgate panel.	1.00	600.00	600.00

400

Amt S\$ 1,680.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,680.00

Repair day - 3 days

Sun Pin (Lkk)

PIP

before part photo

Sunpin@Lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remark Subtotal S\$ 0.00
Parts Subtotal S\$ 5,898.20
Special nett Subtotal S\$ 370.00
Labour Subtotal S\$ 1,680.00
Total S\$ 7,948.20