

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0703/2020/NS
DATE	:	28-Sep-20
WIP	:	50853

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS JIANG MINGXIA
ADDRESS	:	72 SAINT PATRICK'S ROAD #03-10 SINGAPORE 424177
TELEPHONE	:	HP +65 94789808
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070117315
VEHICLE NO	:	SMU 4060 K
MODEL CODE	:	AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR	:	12/8/2020
ENGINE NO	:	CZD 896309
CHASSIS NO	:	WAUZZZF37L1109540
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	25-Sep-20
PLACE OF ACCIDENT	:	AYE EXIT 2A

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 4060 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 X	
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 560.00 X	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS AND REINSTALL ALL PARTS REMOVED.	\$ 3,000.00 ✓ 1500.	
5	TO RESPRAY FRONT BUMPER ✓, RHS FRONT FENDER ✓, RHS FRONT DOOR ✓, RHS REAR DOOR ✓, RHS WING MIRROR COVER AND DOOR HANDLE.	\$ 3,000.00 ✓ 2450.	4 x 550 = 2200 Mirror = 150. Handle = 100
SUB TOTAL LABOUR CHARGES		: \$ 7,240.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 4060 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	X
7	TO RENEW RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 300.00	X
8	TO INSTALL SOLAR FILM FOR RHS REAR 1/4 GLASS.	S/N \$ 400.00	X
9	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N \$ 200.00	X
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	X
SUB TOTAL LABOUR CHARGES		: <u>\$ 2,660.00</u>	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 4060 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAG COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	X
12	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER AND REAR OUTER END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,500.00	500
13	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 3,575.00	550
14	TO RENEW RHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 320.00	280
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 20,887.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 4060 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Repaired</i>	\$	2,045.00	✓
2 FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	\$	58.00	+
3 FRONT SPOILER <i>cut</i>	\$	379.00	✓
4 FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	\$	151.00	+
5 FRONT BUMPER GRILLE - RH <i>new</i>	\$	109.00	+
6 FRONT WHEEL COVER - LH / RH <i>LH new, RH 1/2</i>	\$	530.00	✓
7 FRONT BUMPER GUIDE SECTION - RH <i>?</i>	\$	38.00	?
8 FRONT FENDER - RH <i>Dented</i>	\$	1,271.00	✓
9 FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	62.00	+
10 FRONT FENDER BRACE - RH <i>?</i>	\$	87.00	?
11 FRONT FENDER BRACKET - RH <i>?</i>	\$	31.00	?
12 FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$	237.00	+
13 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	100.00	+
14 HEADLIGHT MOUNTING - RH <i>new</i>	\$	117.00	+
15 LED HEADLIGHT - RH <i>new</i>	\$	5,526.00	✓
16 LIFT CYLINDER - RH <i>new</i>	\$	208.00	+
17 FRONT DOOR - RH <i>Repair</i>	\$	2,542.00	+
18 FRONT DOOR OUTER SEAL <i>new</i>	NEC \$	164.00	+
19 FRONT DOOR CATCH <i>new</i>	\$	119.00	+
20 FRONT DOOR ATTACHMENT PARTS <i>new</i>	\$	155.00	+
SUB TOTAL SPARE PARTS	:	\$	13,929.00



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 4060 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT DOOR COVER - RH <i>new</i>		\$ 265.00	+
22 EXTERIOR MIRROR MOUNTING - RH <i>ut</i>		\$ 2,041.00	✓
23 MIRROR CAP - RH <i>Regrt ut</i>		\$ 167.00	✓
24 MIRROR GLASS - RH <i>new</i>		\$ 977.00	+
25 EXTERIOR DOOR HANDLE - RH <i>Regrt</i>		\$ 701.00	+
26 DOOR HANDLE CAP <i>new</i>		\$ 27.00	+
27 REAR DOOR - RH <i>Regrt</i>		\$ 2,639.00	+
28 REAR DOOR OUTER SEAL <i>new</i>	NEC	\$ 134.00	✓
29 REAR DOOR CATCH <i>new</i>		\$ 119.00	+
30 SILL PANEL SEAL - RH <i>new</i>		\$ 134.00	+
31 REAR DOOR ATTACHMENT PARTS <i>new</i>		\$ 307.00	✓
32 REAR DOOR COVER - RH <i>ut</i>		\$ 254.00	✓
33 REAR FENDER - RH <i>Regrt</i>		\$ 3,204.00	+
34 SIDE WINDOW - RH <i>new</i>		\$ 607.00	✓
35 REAR BUMPER <i>new</i>		\$ 1,465.00	+
36 REAR BUMPER SPOILER <i>new</i>		\$ 454.00	+
37 REAR BUMPER FIXING PARTS <i>new</i>		\$ 209.00	+
38 REAR CROSS REINFORCEMENT - CENTRE <i>new</i>		\$ 96.00	+
39 REAR BUMPER GUIDE SECTION - RH <i>new</i>		\$ 63.00	+
40 REAR CROSS PANEL <i>new</i>		\$ 308.00	+
SUB TOTAL SPARE PARTS	:	\$ 14,171.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 4060 K

S/N PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41 REAR WHEEL COVER - LH / RH	2	\$	530.00	265
42 ALUMINIUM RIM - RH FRONT / REAR	2	\$	1,512.00	758
43 1/4 GLASS SEALANT	S/N	\$	100.00	X
44 METAL FILLER POWDER	S/N	\$	280.00	X
45 STONE CHIP	S/N	\$	180.00	X
46 CAVITY WAX	S/N	\$	140.00	X
47 ACRYLIC SEALANT	S/N	\$	180.00	X
48 SUNDRIES	?	\$	400.00	?
TOTAL SPARE PARTS	:	\$	31,422.00	
TOTAL LABOUR CHARGES	:	\$	20,887.00	
GRAND TOTAL	:	\$	52,309.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME

:

Adrian Ly

SURVEYED DATE

:

29/09/20

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 88 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Consultant's hence notify the Rep on the following:

- To resurvey (e.g. after spray painting)
- To display (e.g. parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT