

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	25 Sep 2020 12:34	Clm Veh Model Changed	(200049) AUDI A6 2.0 TFSI (A).	[] Merimen Administrator
2	25 Sep 2020 12:34	Clm Created	Reg No: SKP8396R. Policy No: 2070125093. Acct Date: 2020/09/24. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA120083548	[I] Merimen Administrator
3	30 Sep 2020 09:10	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	30 Sep 2020 09:10	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	30 Sep 2020 09:10	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	30 Sep 2020 09:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/10/09	[A] LEE SU THING
7	30 Sep 2020 09:10	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	30 Sep 2020 09:10	Clm Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	30 Sep 2020 09:11	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
10	30 Sep 2020 10:20	Adj Rpt Initiated		[A] SHIAU CHAN
11	30 Sep 2020 10:20	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] SHIAU CHAN
12	30 Sep 2020 10:20	Clm Dtl Modified	JPJ Reg. Date: -> 2020/08/26.	[A] SHIAU CHAN
13	30 Sep 2020 10:20	Clm Details Notified		[A] SHIAU CHAN
14	30 Sep 2020 10:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/10/09	[A] SHIAU CHAN
15	30 Sep 2020 10:58	Adj Mandate Request	Cur.Req:4403.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] SHIAU CHAN
16	30 Sep 2020 16:24	Clm Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 800.00. Excess Waived: -> 800.00. 2F Remarks: -> Not Applicab le. GST: -> 7.00.	[I] Azlan, Syazairdina
17	30 Sep 2020 16:24	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	01 Oct 2020 14:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/10/09. Mandate Remarks: Authorise repair. Labour 1 not necessary bumper repair. Re-inspection to be done for damage check and supplementary items / labour with clear photos.	[I] Koh, Victor-CK
19	01 Oct 2020 14:55	Adj Mandate Set	Approved:4203.00:Authorise repair. Labour 1 not necessary bumper repair. Re-inspection to be done for damage check and supplementary items / labour with clear photos. Reinsp:Yes.	[I] Koh, Victor-CK

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2598562	30 Sep 2020 10:20:07	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKP8396R		11.00

