

Car-in 26/10/2020 wip. 50782

PREMIUM AUTOMOBILES

Kiam/Hong



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Xiao Chen

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKP 8396 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Repair</i>	\$	2,763.00	
2 FRONT BUMPER FIXING PARTS <i>Repair</i>	\$	643.00	
3 FRONT BUMPER CLOSING ELEMENT - CENTRE <i>crackd</i>	\$	220.00	✓
4 FRONT BUMPER ADAPTER - LH <i>crackd</i>	\$	39.00	✓
5 FRONT BUMPER REINFORCEMENT BRACKET - LH <i>NAP</i>	\$	110.00	
6 FRONT BUMPER GRILLE - LOWER CENTRE <i>Repair</i>	\$	151.00	
7 FRONT BUMPER CLOSING ELEMENT - LOWER <i>Repair</i>	\$	208.00	
8 FRONT BUMPER SPOILER <i>Repair</i>	\$	249.00	
9 FRONT BUMPER AIR GUIDE GRILLE - LH <i>Cr</i>	\$	429.00	
10 FRONT BUMPER SIDE AIR GUIDE - LH LOWER <i>Repair</i>	\$	28.00	
11 FRONT BUMPER SIDE AIR GUIDE - LH UPPER <i>Repair</i>	\$	21.00	
12 RADIATOR GRILLE <i>Cr</i>	\$	2,192.00	
13 RADIATOR GRILLE COVER <i>Repair</i>	\$	54.00	
14 RADIATOR GRILLE COVER CAP	\$	88.00	
15 RADIATOR GRILLE BRACKET	\$	92.00	
16 FRONT BUMPER CARRIER <i>Repair</i>	\$	960.00	
17 FRONT BUMPER SUPPORT	2 \$	59.00	
18 FRONT BUMPER GUIDE SECTION - LH <i>Repair</i>	\$	44.00	
19 FRONT BUMPER BRACKET - LH <i>Repair</i>	\$	54.00	
20 FRONT BUMPER COVER <i>Repair</i>	\$	124.00	
SUB-TOTAL SPARE PARTS	:	\$ 8,528.00	

Remyd.
Adrian L.
29/10/20.
H.S.

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.