



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD C/O: LOW YEAP TOH & GOON 10 ANSON ROAD #18-13 INTERNATIONAL PLAZA SINGAPORE 079903			Ref: CS/LAW20010462/AT1vf3e2 Date: 22/03/2021	Code: INC3
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	PA 9660R	Veh. Inspected	SLK 8494E	
Policy No.		Coverage (\$)	0.00	
Claim No.	GEP.2304.04.20.ct	Excess (\$)	0.00	
Assign From	SITI MARINA	Assign Date	29/09/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	PORSCHE PANAMERA	c.c	3605	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WP0ZZZ97ZBL003273	Colour	WHITE	
Odometer	107365 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	255/40 R20	MICHELIN	6 mm	
L/H Front Tyre	255/40 R20	MICHELIN	6 mm	
R/H Rear Tyre	255/40 R20	MICHELIN	6 mm	
L/H Rear Tyre	255/40 R20	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/03/2018	Inspection Date	26/11/2020	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	