

LKK
Khoochae

Not Authorized
d/s \$3000/
4 days.

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

VEHICLE No: GBD 3195G

more item

1PC	TAILGATE
1PC	TAILGATE ,NISSAN, EMBLEM
1PC	TAILGATE LOWER MEMBER
2PCS	TAILGATE LOCK LATCHS @215.00
2PCS	TAILGATE HINGES \$50.00
2PCS	TAILGATE 'L' LOWER PANELS @145.00
2PCS	TAILGATE 'L' LOWER PANEL STOPPERS @121.00
2PCS	TAILLAMPS @208.00
2PCS	TAILLAMP BRACKERS @165.00
2PCS	DROP SIDEGATES @2998.00
1PC	CHASSIS FRAME MEMBER
1PC	REAR LICENCE PLATE BRACKET
1PC	REAR SPARE TYRE BRACKET & CHAIN

R	\$2,668.00	X
11	\$175.00	X
20/30/1	\$688.00	X
2	\$430.00	X
2	\$100.00	X
2	\$290.00	X
11	\$242.00	X
one	\$416	—
11	\$330.00	X
2	\$5,996.00	X
2	\$3,800.00	X
20/1	\$108.90	—
20/1	\$399.90	—
	\$15,643.80	

10%

	S.NETT
1SET	70KM/H STICKER & 13 PAX STICKER
1SET	REAR REVERSE SENSOR
1SET	TAILGATE CORPARATE STICKER
1PC	REAR LICENCE PLATE

20/1	\$25.00	20
one	\$280.00	200
20/1	\$500.00	✓
20/1	\$15.00	✓

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS	\$880.00	X
TO SPRAY RUST PROOFING	\$180.00	40
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00	800
TO PUTTY & SPRAY PAINTING	\$1,800.00	600

TOTAL \$21,253.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

2-1612.80
10%
P-1451.52
S.W-735.00
L-1600.00
3786.52
3019