LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur Date: 09 Oct 2020

Preliminary Advice

 Vehicle No
 : SKL3323E
 Accident Date
 : 29/09/2020

 Make
 : AUDI A5
 Policy No.
 : 1900084874-01

Assignment Date : 30/09/2020 Excess : \$\$0.00 Date of Inspection : 30/09/2020 Est. Duration of Repair : 12

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 47,372.00 (inclusive supp \$14,306.00)

Revised Amount :S\$ 26,926.00 (inclusive supp)

Check Items (Estimated) :S\$ 11,052.00
Total :S\$ 37,978.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 156,000.00 COE / PARF Rebate :S\$ 70,789.00

Salvage Value :S\$

Margin for Repair :S\$ 85,211.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confir	med excess and policy coverage.
	Kindly let us have your authorisation.	

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Kindly approve on supplementary.