

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 26 Oct 2020

Preliminary Advice

Vehicle No	: SKL3323E	Accident Date	: 29/09/2020
Make	: AUDI A5	Policy No.	: 1900084874-01
Assignment Date	: 30/09/2020	Excess	: S\$0.00
Date of Inspection	: 30/09/2020	Est. Duration of Repair	: 12
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,572.00 (inclusive supp 1 \$14,306.00 + supp
Revised Amount	:S\$	28,483.00 (inclusive supp 1 + 2)
Check Items (Estimated)	:S\$	9,695.00
Total	:S\$	38,178.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	156,000.00
COE / PARF Rebate	:S\$	70,789.00
Salvage Value	:S\$	
Margin for Repair	:S\$	85,211.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on supplementary 2.