



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

ST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0710/2020/NS

Date

20-Oct-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKL 3323 E

Model No

AUDI A5 SPORTSBACK 2.0 TFS

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To install sticker for rear bumper chrome trim. <i>new</i>	s/n \$ 200.00	✓

TOTAL

\$ 200.00

*Resmryed
21/10/20
Adrian
Sip*

Car-in

wip: 51284

Kam / Keong

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 3323 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>Rehnd</i>		\$	2,504.00	✓
2 REAR BUMPER FIXING PARTS <i>new</i>		\$	163.00	✓
3 REAR BUMPER SECURING STRIP <i>new</i>		\$	220.00	✓
→ 4 REAR BUMPER CHROME TRIM <i>changed</i>		\$	1,005.00	✓
5 REAR LIGHT REFLECTOR - LH / RH <i>new</i>	2	\$	82.00	✓
6 LED TAIL LIGHT - LH / RH OUTER <i>cut</i>	2	\$	2,258.00	✓
7 TAIL LIGHT TRIM - LH / RH OUTER <i>cut</i>	2	\$	60.00	✓
8 LED TAIL LIGHT - LH / RH INNER <i>changed</i>	2	\$	2,016.00	✓
9 TAIL LIGHT TRIM - LH / RH INNER <i>cut</i>	2	\$	60.00	✓
10 LED LICENSE PLATE LIGHT <i>changed</i>	2	\$	100.00	✓
11 ADDITIONAL BRAKE LIGHT		\$	570.00	
12 REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2		TBC	✓
13 REAR BUMPER CARRIER		\$	886.00	
14 REAR BUMPER CARRIER SEAL	2	\$	28.00	
15 REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	44.00	✓
16 REAR LID <i>Rehnd</i>		\$	3,080.00	✓
17 REAR LID HINGE - LH / RH	2	\$	452.00	?
18 REAR LID ATTACHMENT PARTS		\$	152.00	?
19 REAR LID LOCK <i>changed</i>		\$	241.00	✓
20 BONET LOCK COVER <i>cut</i>		\$	12.00	✓
SUB TOTAL SPARE PARTS		\$	13,933.00	

Resigned
Admin by
H.P.

21/10/20.