

AUTO SPRINT

24 Leng Kee Road
Leng Kee Auto Point
#07-01
Singapore 159096

Krasul
Hp 90010068
4 days
L/S
07/10/2020 @ 1600
Reins after repair

TO: FIRST CAPITAL
ATTN.: MOTOR CLAIMS DEPARTMENT
OUR REF.: SBQ 8942 R
YOUR REF.: SHB 4057 E

DATE: 3 October 2020
CREATED BY: CASSANDRA CHUA
CONTACT NO.: 9820 7448
VEHICLE NO.: SBQ 8942 R
MAKE & MODEL: MITSUBISHI PAJERO
CHASSIS NO.: JMAL047GWLJ450344
ENGINE NO.: 4G54KN1514
YEAR: 1991
DATE OF ACC.: 25/9/2020
CLAIM TYPE: TP

ESTIMATE FOR VEHICLE NO.: SBQ 8942 R

NO.	DESCRIPTION	QTY.	LIST PRICE
PARTS			
1	TAILLAMP RH <i>scr</i>	1	\$ 1,380.92
2	REAR BUMPER <i>X</i>	1	\$ 952.20
3	REAR BUMPER CLIP <i>X</i>	10	\$ 70.00
4	REAR BUMPER LOWER DIFFUSER RH <i>scr</i>	1	\$ 489.20
5	REAR FENDER RH <i>repair</i>	1	\$ 1,130.50
6	REAR FENDER ARCH COVER RH <i>scr</i>	1	\$ 298.61
7	REAR DOOR RH <i>X</i>	1	\$ 998.43
8	REAR DOOR ARCH COVER RH <i>repair</i>	1	\$ 302.12
9	FRONT FENDER RH <i>repair</i>	1	\$ 1,128.21
SUBTOTAL:			\$ 6,750.19

LESS 10%: \$ 675.02
PARTS TOTAL: \$ 6,075.17

SPECIAL NETT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SPECIAL NETT TOTAL: \$ -

LABOUR

TO REMOVE, REPAIR & INSTALL ALL ACCIDENT AFF. PORTIONS	\$ 1,000.00	<i>400</i>
TO CHECK ENGINE WARNING LIGHT (ABS, ECU, & ETC.)	\$ 250.00	<i>X</i>
TO CHECK ALL NECESSARY WIRING	\$ 180.00	<i>30</i>
TO PUTTY & RESPRAY ALL ACCIDENT AFF. PORTIONS	\$ 1,300.00	<i>500</i>
TO APPLY ANTI-RUST COATING ON ALL ACCIDENT AFF. PORTIONS	\$ 350.00	<i>X</i>

LABOUR TOTAL: \$ 3,080.00

GRAND TOTAL: \$ 9,155.17

BEFORE 7% GST