

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : EMILDA BINTE SULAIMAN
471A UPPER SERANGOON CRESCENT
#08-382
SINGAPORE 531471
TEL: 93369195
ATTN:

Estimate No: MC1901446
Date: 30 Sep 2020
Policy No: MT/00845858
Veh Reg No: SLC5470K
Make/Model: MAZDA 3 4-DOOR
SEDAN 1.5L

Your Ref No: SLC5470K
Claim Type: Third Party
Accident Date: 28/09/2020
TP Veh Reg No: SHC2548M

Estimate Repair Cost to Vehicle No :SLC5470K

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR BUMPER	1 PC	996.70	
2 REAR BUMPER TOW COVER LH	1 PC	16.50	
3 REAR BUMPER SIDE RETAINER LH	1 PC	38.00	
4 REAR BUMPER CLIPS	12 PC	36.00	
5 REAR BUMPER REINFORCEMENT	1 PC	564.20	
6 REVERSE SENSOR INNER LH & RH	2 PC	407.20	
7 REVERSE SENSOR HOLDER	4 PC	72.80	
8 REAR BOOT LOCK	1 PC	160.70	
9 REAR FENDER COWLING LH	1 PC	153.10	
10 REAR FENDER COWLING CLIPS	4 PC	12.00	
11 TAILAMP LH	1 PC	866.80	
		3,324.00	
	Less 20%	664.80	2,659.20
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
14 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
15 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR END PANEL,RR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
16 TO SPRAY REAR BUMPER,REAR FENDER LH,END PANEL.	1 PC	600.00	
		1,260.00	1,260.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : EMILDA BINTE SULAIMAN
471A UPPER SERANGOON CRESCENT
#08-382
SINGAPORE 531471
TEL: 93369195
ATTN:

Estimate No: MC1901446
Date: 30 Sep 2020
Policy No: MT/00845858
Veh Reg No: SLC5470K
Make/Model: MAZDA 3 4-DOOR
SEDAN 1.5L

Your Ref No: SLC5470K
Claim Type: Third Party
Accident Date: 28/09/2020
TP Veh Reg No: SHC2548M

Estimate Repair Cost to Vehicle No :SLC5470K


Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 3,919.20
		Add GST @ 7%	274.34
		Total Amount Payable	S\$ 4,193.54

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED NINETY THREE AND CENTS FIFTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 354E

Vehicle Details

Vehicle No.: SLC5470K
Vehicle to be Exported: No
Intended Deregistration Date: 28 Sep 2020
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour: Red
Manufacturing Year: 2016
Engine No.: P520360465
Chassis No.: JM6BM42A8G0339213
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$18,864.00
Original Registration Date: 18 May 2016
First Registration Date: 18 May 2016
Transfer Count: 1
Actual ARF Paid: \$13,864.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 May 2026
PARF Rebate Amount: \$10,398.00

Intended COE Rebate Details

COE Expiry Date: 17 May 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$49,000.00
COE Rebate Amount: \$26,983.00
Total Rebate Amount: \$37,381.00

The information contained herein is correct as at 28 Sep 2020

OK