

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:40

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016039 Date : 02/03/2021 Order : SMS9563D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMS9563D (V 43779) Regn Date: 23/03/2020 Mileage: 5911 WIP No.: 51427
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V1LA004278 Engine: CHZ C34759 Dept: U
You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
Q	OTHERS	M: TO REPLACE FRONT NO. PLATE	60.00	1.00	60.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	250.00	1.00	250.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET AND RHS FRONT FENDER.	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V5807065R GRU	COVER	Less 020%	1.00	1987.00
X	A8V5807534A	COVERSTRIP	Less 020%	1.00	160.50
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1406.00
X	A8V0010515A	STICKER	Less 020%	1.00	7.10
X	A8K0010520C	STICKER	Less 020%	1.00	13.50
X	A8V5821106A	FENDER	Less 020%	1.00	841.00
X	A8V0941774D	HEADLIGHT	Less 020%	1.00	5455.00
X	AN 0161857	POP-RIVET	Less 020%	5.00	3.20
X	A8V0807550A	FOAM INSER(LAST) AP	Less 020%	1.00	187.00
X	A8V3853949	PLATE AP	Less 020%	1.00	188.50
X	A8V0821136A	SUPPORT AP	Less 020%	1.00	94.60

Parts 8,284.96
Labour 60.00
Sublet 3,372.00
Menus 0.00
Lubricant 0.00

Sub-Total 11,116.96

7% GST 778.19

Grand Total 11,895.15



Received by

For & on behalf of
Premium Automobiles Pte Ltd