

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s 1 hrs Perry
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Veh No: SLV 0253P Yr Regn: 01, 18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mit Attrage C.C. 1193
 Colour: M Red A/C: Insured / Std / Nil / NA
 Sp. Reading: 14016 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: NMBSTA13AJ14000854
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/55R15
 R: _____
 DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 7 mm Rear R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 30/9/20 D.O.I. 5/10/2020
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear body
 The U/C / Chassis frame / Body structure affected due to collision.

Date / Time	Action / Instruction
<u>15/10</u>	<u>L1 Rm @ 3450k Car frame</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

1) Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
S - RS. \$	
Fees	
Others	
TOTAL	

Report Format : _____
 Lump Sum / I.B.I: (\$)

HWA SENG SPRAY PAINTING PTE LTD
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO : 202017045G)
 TEL : 64533100
 FAX : 62669932

Date of Accident: 30/09/2020

You Insured

Vehicle No. : SMS 9563D

*Not authorized
 After
 Repairing by paint
 C1 Sup @ 3450hr 6 days*

ESTIMATE REPAIR COST TO MITSUBISHI ATTRAGE REG. NO. : SLV 6253 P

		S\$	
1pc	Right Rear Door	1009.00	✓
1pc	Right Rear Panel	823.00	✓
1pc	Right Rear Inner Shield	55.00	x
1pc	Right Rear Door Rubber	181.00	x
1pc	Right Rear Sport Rim	285.00	x
1pc	Rear Bumper 2	708.00	✓ 608
1pc	Door Sticker	47.00	—
		3108.00	
	Less : 10%	310.80	
		2797.20	

LABOUR & MISC CHARGES

Panel Knocking	900.00	<i>800</i>
Spray Painting	1000.00	<i>660</i>
Wire Checking	50.00	<i>20</i>
Labour to Remove & Install Rear Windscreen	160.00	<i>120</i>
Sealant & Clip	80.00	<i>60</i>
Inner Seal	60.00	<i>30</i>
Labour to Transfer Door Trim & Attach Part	100.00	<i>60</i>
Computerised Wheel Alignment	120.00	<i>60</i>
		5267.20
TOTAL		

HWA SENG SPRAY PAINTING PTE LTD

A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: