

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 83220017

TP Budget Direct
Xiao Chen

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code : CLM16470

Date in : 01/10/2020

Vehicle Num. : SLM4772T

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1917580/HRA2405904A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	755.40	✓ 755.40
REAR BUMPER REFLECTOR L/R <i>canld</i>	2	55.00	✓ 110.00
REAR BUMPER REINFORCEMENT <i>Best</i>	1	619.20	✓ 619.20
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Best</i>	2	126.00	✓ 252.00
REAR BUMPER SIDE RETAINER L/R <i>He</i>	2	35.90	✓ 71.80
REAR BUMPER SPONGE <i>canld</i>	1	126.40	✓ 126.40
REAR BUMPER TOW HOOK COVER <i>Rehd</i>	1	16.80	✓ 16.80
REAR END PANEL <i>Dented</i>	1	482.60	✓ 482.60
REAR END PANEL ANTENNA SENSOR <i>canld</i>	1	285.10	✓ 285.10
REAR END PANEL TOP GARNISH <i>canld</i>	1	63.50	✓ 63.50
REAR FENDER ARCH GARNISH L/R <i>canld</i>	2	483.00	✓ 966.00
REAR TAILGATE <i>Reps</i>	1	2980.00	X 2,980.00
REAR TAILGATE 'QASHQAI' EMBLEM <i>He</i>	1	87.00	✓ 87.00
REAR TAILGATE WEATHER STRIP <i>He</i>	1	158.70	+ 158.70
REAR TAILLAMP L/R <i>RH canld</i>	2	323.70	32370 647.40

*** This is a computer-generated document which requires no signature.***

4159.5
3743.55

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 83220017

ESTIMATE

Repair Code : CLM16470

Date in : 01/10/2020

Vehicle Num. : SLM4772T

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1917580/HRA2405904A

		Subtotal before discount	7,621.90
Percentage discount	10%		762.19
		Sub-total 1	6,859.71
REAR BUMPER CLIPS - SET	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR - SET	1	450.00	2400 450.00
REAR END PANEL TOP GARNISH CLIPS - SET	1	30.00	10 30.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET	2	20.00	40.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	10 60.00
		Subtotal before discount	630.00
Percentage discount	0%		0.00
		Sub-total 2	630.00
		Parts-total	7,489.71

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

2,960.00

Parts & Labour Total

10,449.71

total: 3633.55
L/S: 4 SK

Admin
w/s 01/10/20. 05eq.

1400
80.00
60 120.00
600 1,200.00
60 80.00
X 80.00