



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0719/2020/NS
DATE	:	1-Oct-20
WIP	:	51481

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR ROCKY YULIANTO SAPUTRA
ADDRESS	:	BLK 88 TELOK BLANGAH HEIGHTS #19-357 SINGAPORE 100088
TELEPHONE	:	HP +65 90678100
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900020101
VEHICLE NO	:	SMJ 3626 T
MODEL CODE	:	AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR	:	28/2/2019
ENGINE NO	:	CHZ C26035
CHASSIS NO	:	WAUZZZ8V0KA028716
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	30-Sep-20
PLACE OF ACCIDENT	:	PIE TOWARDS TUAS(AFTER SIMEI)



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3626 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED.	\$ 1,000.00	500
3	TO RESPRAY FRONT BUMPER.	\$ 1,100.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,572.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3626 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Replaced</i>	\$	1,842.00	✓
2 FRONT BUMPER FIXING PARTS <i>Re u</i>	\$	185.00	+
3 FRONT BUMPER GUIDE SECTION - LH / RH <i>Re u 2</i>	\$	76.00	+
4 FRONT BUMPER GRILLE - CENTRE <i>Replaced</i>	\$	159.00	✓
5 FRONT BUMPER GRILLE CLOSING ELEMENT - LOWER CENTRE <i>Not Re</i>	\$	293.00	+
6 FRONT BUMPER CLOSING ELEMENT - LH / RH <i>Re u 2</i>	\$	586.00	+
7 RADIATOR GRILLE <i>Replaced</i>	\$	1,406.00	✓
8 RADIATOR GRILLE CLOSING ELEMENT <i>Re u</i>	\$	189.00	
9 FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LT Replaced</i>	\$	372.00	186.
10 FRONT REINFORCEMENT BEAM <i>Re u</i>	\$	715.00	+
11 FRONT BUMPER FOAM FILLER PIECE <i>Re u</i>	\$	187.00	+
12 FOAM FILLER PIECE COVER <i>Re u</i>	\$	121.00	+
13 AIRCON STICKER <i>3 Nec</i>	NEC \$	8.00	✓
14 CAUTION SIGN STICKER <i>1 Nec</i>	NEC \$	14.00	✓
15 SIGNAL HORN - LH HIGH TONE <i>3 Re u</i>	\$	197.00	x
16 SIGNAL HORN - RH LOW TONE <i>1 Re u</i>	\$	197.00	+
17 LED HEADLIGHT - LH / RH <i>2</i>	2 \$	10,910.00	x
18 LIFT CYLINDER - LH / RH <i>Re u</i>	2 \$	282.00	✓
19 LIFT CYLINDER HOSE <i>Re u</i>	\$	67.00	x
20 RADIATOR AIR GUIDE - LH / RH <i>Not Re</i>	2 \$	48.00	+
SUB TOTAL SPARE PARTS	:	\$ 17,854.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3626 T

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 RADIATOR AIR GUIDE - UPPER CENTRE <i>Alt m</i>	\$	12.00	<i>+</i>
22 BONNET CATCH HOOK <i>Alt m</i>	\$	63.00	<i>x</i>
23 FRONT NO PLATE <i>Nec</i>	S/N \$	60.00	<i>✓</i>
24 SUNDRIES <i>?</i>	\$	200.00	<i>?</i>
TOTAL SPARE PARTS	:	\$ 18,189.00	
TOTAL LABOUR CHARGES	:	\$ 2,572.00	
GRAND TOTAL	:	\$ 20,761.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *02/10/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT