



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. AC2007264
INV Date 30/10/2020
Reference CS3/III20010600/Eyf3s2
Code III2



PROFESSIONAL SERVICE FEE

Vehicle No. SJF 7884U
Insured Veh. SKG 1132D
Claim No.
Policy No. D20MPC0000804
Accident Date 23/09/2020
Inspection Date 08/10/2020

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 08.10.2020 02.02pm	
- Dismantle Inspection 09.10.2020 11.30am	
- After Repair Inspection 12.10.2020 1.30pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd