



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20010602/R1qd3e2

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Date : 10-12-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBR 2078U	Veh. Inspected	SMQ 6467D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002882/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	02/10/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X3 SDRIVE20I	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WBATR120X09A50597	Colour	BLACK
Odometer	11949	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R19	BRIDGESTONE	6 mm
L/H Front Tyre	245/50 R19	BRIDGESTONE	6 mm
R/H Rear Tyre	245/50 R19	BRIDGESTONE	6 mm
L/H Rear Tyre	245/50 R19	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/10/2020	Inspection Date	26/10/2020
Survey held at	9A SERANGOON NORTH AVE 5		
Repairer	PERFORMANCE MOTORS LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------