



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Ref: CS/GAI20010603/R1qf3e2 Date: 12/01/2021 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 3950Z	Veh. Inspected	SLG 9362S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003890	Excess (\$)	0.00	
Assign From	MOTOR CLAIM	Assign Date	02/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0344829	Colour	GREY	
Odometer	73842 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/09/2020	Inspection Date	06/10/2020	
Survey held at	27A Tanjong Penjuru			
Repairer	TRANS EUROKARS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	