



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:JANICE

Ref: CC4/ASM20010657/Kes3q2  
Date: 10/01/2022  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLE 4580Y	<b>Veh. Inspected</b>	SML 37C
<b>Policy No.</b>	GA494984	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S0M02SP9	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	05/10/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	PORSCHE MACAN (A)	<b>c.c</b>	1984
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	WP1ZZZ95ZGLB05403	<b>Colour</b>	METALLIC PEARL PINK
<b>Odometer</b>	45800 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	235/60 R18	PIRELLI	8 mm
<b>L/H Front Tyre</b>	235/60 R18	PIRELLI	8 mm
<b>R/H Rear Tyre</b>	255/55 R18	PIRELLI	8 mm
<b>L/H Rear Tyre</b>	255/55 R18	PIRELLI	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	24/08/2020	<b>Inspection Date</b>	06/10/2020
<b>Survey held at</b>	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**