

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0726/2020/NS
DATE : 2-Oct-20
WIP : 51718

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS QIN XIANG
ADDRESS : 33 PASIR RIS DRIVE 3
#05-04
SINGAPORE 519492
TELEPHONE : HP +65 83037290
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900256402
VEHICLE NO : **SMR 296 P**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 14/12/2019
ENGINE NO : CHZ C35258
CHASSIS NO : WAUZZZ8V0LA002554
MILEAGE : 12416KM
DATE IN : 2-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Oct-20
PLACE OF ACCIDENT : DECATHLON BEDOK CARPARK D

14 days

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 296 P**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$	280.00	X
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O- LINER.	S/N \$	800.00	?
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	280.00	X
4	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
5	TO PLACE VEHICLE ON CAR O-LINER.	S/N \$	1,800.00	?
6	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FORDAMAGES.	S/N \$	560.00	✓
SUB TOTAL LABOUR CHARGES		:	\$ 4,070.00	


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 296 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS HEADLIGHT, LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,000.00	2600
8	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR AND HANDLES.	\$ 3,700.00	2450
9	TO DISLODGE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	X
10	TO RENEW LHS FRONT AND REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 320.00	280
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,682.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER		\$ 1,987.00	xnn
2 FRONT BUMPER FIXING PARTS		\$ 185.00	xnn
3 FRONT BUMPER GUIDE SECTION - LH		\$ 38.00	xnn
4 FRONT FENDER - LH		\$ 841.00	✓00
5 FRONT FENDER ATTACHMENT PARTS		\$ 71.00	xnn
6 FRONT FENDER BRACKET - LH		\$ 38.00	xnn
7 FRONT FENDER BRACE - LH		\$ 95.00	xnn
8 FRONT WHEEL HOUSING LINER - LH		\$ 167.00	xnn
9 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	xnn
10 LED HEADLIGHT - LH		\$ 5,455.00	xnn
11 FRONT DOOR - LH		\$ 2,494.00	✓00
12 FRONT DOOR OUTER SEAL	NEC	\$ 159.00	/nec
13 BONDING AGENT	NEC	\$ 47.00	?
14 CLEANING SOLUTION	NEC	\$ 65.00	?
15 FRONT DOOR ATTACHMENT PARTS		\$ 238.00	xnn
16 FRONT DOOR CATCH		\$ 104.00	?
17 REAR DOOR - LH		\$ 2,494.00	✓00
18 REAR DOOR OUTER SEAL	NEC	\$ 159.00	/nec
19 BONDING AGENT	NEC	\$ 47.00	?
20 CLEANING SOLUTION	NEC	\$ 65.00	?
SUB TOTAL SPARE PARTS	:	\$ 14,837.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 REAR DOOR ATTACHMENT PARTS		\$ 127.00	xnn
22 REAR DOOR CATCH		\$ 93.00	?
23 SIDE FRAME - LH		\$ 3,436.00	/m
24 SIDE WINDOW - LH		\$ 563.00	/m
25 ALUMINIUM RIM - LH FRONT / REAR	2	\$ 1,397.00	698.50 front cut
26 EXTERIOR MIRROR MOUNTING - LH		\$ 1,001.00	xnn
27 MIRROR CAP - LH		\$ 148.00	x repair
28 MIRROR GLASS - LH		\$ 1,184.00	xnn
29 1/4 GLASS SELANT	S/N	\$ 200.00	?
30 METAL FILLER POWDER	S/N	\$ 280.00	/m
31 STONE CHIP	S/N	\$ 180.00	/m
32 CAVITY WAX	S/N	\$ 140.00	/m
33 ACRYLIC SEALANT	S/N	\$ 180.00	/m
34 SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS	:	\$ 24,266.00	
TOTAL LABOUR CHARGES	:	\$ 12,682.00	
GRAND TOTAL	:	\$ 36,948.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT