

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 06 Oct 2020

Preliminary Advice

Vehicle No	: SMR296P	Accident Date	: 02/10/2020
Make	: AUDI A3	Policy No.	: 1900256402
Assignment Date	: 05/10/2020	Excess	: S\$0.00
Date of Inspection	: 05/10/2020	Est. Duration of Repair	: 30
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	76,662.00
Revised Amount	:S\$	47,532.50
Check Items (Estimated)	:S\$	4,294.00
Total	:S\$	51,826.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	136,460.00
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	47,515.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	88,945.00
Margin for Repair (Pre-Accident Value)	:S\$	65,485.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :