

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0727/2020/NS
DATE	:	2-Oct-20
WIP	:	51689

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS GUO YA-WEN
ADDRESS	:	BLK 673A JURONG WEST STREET 65 #10-28 SINGAPORE 641673
TELEPHONE	:	HP +65 90930988
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070138029
VEHICLE NO	:	SMU 1088 B
MODEL CODE	:	AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR	:	24/9/2020
ENGINE NO	:	DKY 013858
CHASSIS NO	:	WAUZZZF26LN056216
MILEAGE	:	99KM
DATE IN	:	2-Oct-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	28-Sep-20
PLACE OF ACCIDENT	:	ALONG JURONG WEST AVE 1



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 1088 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	X
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00 250	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00 1000	✓
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER.	\$ 3,500.00 1100	✓
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
SUB TOTAL LABOUR CHARGES		: <u>\$ 8,732.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>torn</i>	\$	2,763.00	✓ 2210.40
2 FRONT BUMPER FIXING PARTS <i>not in</i>	\$	643.00	+
3 FRONT BUMPER CLOSING ELEMENT - CENTRE <i>crushed</i>	\$	220.00	? 175.60
4 FRONT BUMPER ADAPTER - LH / RH <i>RH Dmgd</i> 2	\$	78.00	39.6176
5 FRONT BUMPER REINFORCEMENT - RH <i>not in</i>	\$	110.00	+
6 FRONT BUMPER GRILLE - LOWER CENTRE <i>not in</i>	\$	151.00	+
7 FRONT BUMPER CLOSING ELEMENT - LOWER <i>not in</i>	\$	208.00	? X
8 FRONT SPOILER <i>not in</i>	\$	249.00	+
9 FRONT BUMPER AIR GUIDE GRILLE - RH <i>crushed</i>	\$	429.00	✓ 343.20
10 FRONT BUMPER AIR GUIDE - RH UPPER <i>crushed</i>	\$	28.00	✓ 22.32
11 FRONT BUMPER AIR GUIDE - RH LOWER <i>crushed</i>	\$	21.00	✓ 16.08
12 RADIATOR GRILLE <i>crushed</i>	\$	2,192.00	✓ 1753.60
13 RADIATOR GRILLE COVER <i>not in</i>	\$	54.00	? X
14 CONNECTOR HOUSING BRACKET - LH <i>not in</i>	\$	28.00	+
15 FRONT BUMPER CARRIER <i>not in</i>	\$	960.00	+
16 FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	\$	223.00	✓ 178.40
17 FRONT BUMPER SUPPORT <i>Not in</i> 2	\$	59.00	? X
18 FRONT BUMPER GUIDE SECTION - RH <i>not in</i>	\$	44.00	✓ 34.72
19 FRONT BUMPER BRACKET - RH <i>Dmgd</i>	\$	54.00	? 42.72
20 FRONT BUMPER COVER <i>crushed</i>	\$	124.00	✓ 99.20
SUB TOTAL SPARE PARTS	:	\$ 8,638.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21 CAUTION SIGN STICKER <i>NEC</i>	NEC	\$	14.00	✓ 10.80
22 OIL COMPLY STICKER <i>NEC</i>	NEC	\$	20.00	+
23 FRONT PARKING AID SENSOR <i>NEC</i> <i>1 piece damaged</i>			TBC	x 193.20
24 FRONT PARKING AID SEAL RING <i>NEC</i>	4	\$	14.00	✓ 10.88
25 FRONT BUMPER WIRING SET <i>NEC</i> <i>Snapped</i>		\$	571.00	x 456.40
26 HORN - RH <i>NEC</i>		\$	214.00	+
27 SPRING SHACKLE - RH <i>NEC</i>		\$	47.00	+
28 FRONT FENDER - RH <i>Distorted</i>		\$	1,451.00	✓ 1160.80
29 FRONT FENDER BRACE - RH <i>Bent</i>		\$	117.00	? 93.60
30 FRONT FENDER BRACKET - RH UPPER <i>NEC</i>		\$	43.00	? X
31 FRONT FENDER ATTACHMENT PARTS <i>NEC</i>		\$	42.00	x
32 WHEEL HOUSING LINER - RH <i>torn</i>		\$	264.00	✓ 210.80
33 WHEEL HOUSING LINER ATTACHMENT PARTS <i>NEC</i>		\$	70.00	? X
34 WHEEL SPOILER - RH <i>NEC</i>		\$	164.00	? X
35 STONE CHIP GUARD - RH <i>NEC</i>		\$	50.00	✓ 39.92
36 FENDER TRIM LOWER BRACKET - RH <i>NEC</i>		\$	40.00	? X
37 BONNET <i>NEC</i>		\$	5,466.00	x
38 BONNET ATTACHMENT PARTS <i>NEC</i>		\$	230.00	+
39 BONNET LID HINGE - LH / RH <i>NEC</i>	2	\$	340.00	+
40 BONNET IMPACT PROTECTION - LH <i>NEC</i>		\$	19.00	+
SUB TOTAL SPARE PARTS		:	\$	9,176.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
41 BONNET IMPACT PROTECTION - RH		\$	20.00	X
42 BONNET IMPACT PROTECTION - CENTRE		\$	44.00	X
43 BONNET STRIKER - LH / RH	2	\$	218.00	X
44 BONNET LID LOCK	2	\$	407.00	X 162.80
45 BONNET BOWDEN CABLE - CENTRE	2	\$	57.00	X 45.52
46 BONNET RELEASE ELEMENT		\$	57.00	X 45.52
47 BONNET RELEASE LEVER		\$	13.00	X
48 HEADLIGHT MOUNTING - LH / RH	2	\$	234.00	X
49 LED HEADLIGHT - LH / RH	2	\$	16,864.00	8432 6745.60
50 LIFT CYLINDER - LH / RH	2	\$	392.00	X
51 LIFT CYLINDER HOSE		\$	175.00	X
52 RADIATOR AIR GUIDE - LH / RH	2	\$	76.00	X
53 RADIATOR AIR GUIDE - UPPER		\$	30.00	X
54 FRONT BUMPER AIR GUIDE GRILLE - LH		\$	429.00	343.20
55 FRONT ALUMINIUM RIM - RH		\$	990.00	791.60
56 FRONT NO PLATE	S/N	\$	60.00	60
57 SUNDRIES		\$	300.00	2064
TOTAL SPARE PARTS	:	\$	38,180.00	
TOTAL LABOUR CHARGES	:	\$	8,732.00	
GRAND TOTAL	:	\$	46,912.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lj
05/10/20

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Xlt Authorised, 05 days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT