

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Rejab, Intan Syazatul Syima

Date: 07 Oct 2020

Preliminary Advice

Vehicle No	: SGC5802X	Accident Date	: 06/10/2020
Make	: KIA CERATO	Policy No.	: 1900263052
Assignment Date	: 06/10/2020	Excess	: S\$0.00
Date of Inspection	: 06/10/2020	Est. Duration of Repair	: 6
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,360.42
Revised Amount	:S\$	11,668.40
Check Items (Estimated)	:S\$	4,053.62
Total	:S\$	15,722.02

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	44,519.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,481.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :