

Vehicle: SBY8900U

Make & Model:

Audi A1

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Boot ✓			\$1550.00	Body PD ✓
2	Rear Boot Emblem ✓			\$98.00	neu ✓
3	Rear Boot "A1" Wording ✓			\$98.00	neu ✓
4	Rear Boot "TFSI" Wording ✓			\$98.00	neu ✓
5	Rear Boot Number Plate Lamp X	2	30.00	\$60.00	11 X
6	Rear Boot Left Taillamp ✓			\$760.00	scr ✓
7	Rear Number Plate ✓			\$40.00 SN	Best 40 S.N
8	Rear Glass Sealant ✓			\$60.00 SN	neu 40 S.N
9	Rear Boot Inner Trim Board X			\$300.00	11 X
10	Rear Boot Inner Trim Board Chips X			\$40.00 SN	11 X
11	Rear Bumper ✓			\$1145.00	PD ✓
12	Rear Bumper Chips ✓			\$40.00 SN	neu 40 S.N
13	Rear Bumper Inner-Sponge Reinforcement ✓			\$420.00	Best ✓
14	Rear End Panel ✓			\$500.00	PD ✓
15	Rear End Panel Garnish ✓			\$400.00	neu ✓
16	Weather Stripe ✓			\$400.00	295 neu ✓
17	Rear Boot Lock X			\$150.00	11 X
18					
19	5 day				
20					
21	not Authorised				
22	date				
23					

2/5 \$5500
5 day.

date: 15/10/2017

Labour				
1	Glass Fixing To remove & refix rear window		\$ 120.00	120
2	Transfer Boot To front Tailgate mechanism		\$ 150.00	60
3	Anti Rust Proof		\$ 80.00	60
4	Check Wiring		\$ 80.00	20
5	Panel Beating		\$ 800.00	600
6	Paint Work To putty & spray painting		\$ 1,000.00	800

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #02-01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6444 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5364
 57
 P- 5095.80
 S.W. 120.00
 L- 1660.00
 6875.80