

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

06/10/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SJL4764X

Veh Model :- SUZUKI SX4 1.6HB AT

Estimate# :- CK421087

Claim # :-

ACC. Date :- 05/10/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	HEADLAMP RH	1 PC	481.60	481.60
2.	HEADLAMP RH	1 PC	369.05	369.05
3.	RADIATOR GRILLE	1 PC	117.30	117.30
4.	RADIATOR GRILLE LOGO	1 PC	20.00	20.00
5.	FRONT BUMPER	1 PC	790.45	790.45
6.	FRONT BUMPER SIDE GARNISH RH	1 PC	48.05	48.05
7.	FRONT BUMPER LOWER SPOILER	1 PC	167.00	167.00
8.	FRONT BUMPER RETAINER RH & LH	2 PCS	20.00	40.00
9.	FRONT BUMPER CLIPS	10 PCS	3.00	30.00
10.	FOG LAMP RH	1 PC	130.95	130.95
11.	SUPPORT PANEL (REPAIR)	1 PC		
12.	FRONT FENDER RH	1 PC	272.20	272.20
13.	FRONT FENDER ARCH MOULDING RH	1 PC	195.85	195.85
14.	FRONT FENDER COWLING RH	1 PC	60.00	60.00
15.	FRONT FENDER COWLING CLIPS	10 PCS	3.00	30.00
16.	FRONT FENDER EMBLEM - VVT	1 PC	15.00	15.00
17.	FRONT FENDER BRACKET RH	1 PC	25.00	25.00
LIST TOTAL S\$				2,792.45
15% DISCOUNT S\$				-418.87
				2,373.58
LABOUR :				
TO KNOCK AND STRAIGHTEN SUPPORT PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION , repair front RH rim				
				600 680.00
SPRAY PAINT BONNET, SUPPORT PANEL, FRONT BUMPER, FRONT FENDERS RH & LH , spray front RH Rim.				
				700 800.00
CHECK WIRING & FOCUS HEADLIGHT				
				30.00
RUST PROOF AFFECTED AREA				
				30.00
LABOUR TOTAL S\$				1,570.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

06/10/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 139233

Veh # :- SJL4764X

Veh Model :- SUZUKI SX4 1.6HB AT

Estimate# :- CK421087

Claim # :-

ACC. Date :- 05/10/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,943.58

GST @ 7 % 276.05

AMOUNT DUE S\$ 4,219.63

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**


LKK.
Lampiran
Resurvey after repair
- WP - 4 days
6/10/20 @ 4pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: