

VOLKSWAGEN CENTRE SINGAPORE

Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
MS
FIRSTCAPITAL INSURANCE
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Ms.
CHAN
MUN SIN
95 PRINCE CHARLES CRESCENT
#23-14
SINGAPORE 159027

Document no.
Document date 05-10-2020
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2020025254/ 1
Job order date 03-10-2020
Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SW23M	AD14PY	14-11-2018	WVGZZZ5NZJW940698	Tiguan 1.4actHLBMTFR 110TSID6F	32,044

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5NA827025L	Rear Trunk Lid	1	pcs.	2,072.20	#1	2,072.20	2,217.25
D 169300M2	1k Window Adhesive	2	pcs.	49.51	#1	99.02	105.95
D 002000A2	Adhesive Remover	1	pcs.	114.78	#1	114.78	122.81
D 00920002	Primer	1	pcs.	25.74	#1	25.74	27.54
D 00950025	Applicator	2	pcs.	9.39	#1	18.78	20.09
D 181802M1	Activator For Precoated W	1	pcs.	23.77	#1	23.77	25.43
8D0853419D	Packing Adhesive	1	pcs.	27.82	#1	27.82	29.77
WHT007341	Rivetted Cap Nut	2	pcs.	2.23	#1	4.46	4.77
5NA853630 FOD	Vw Sign Black High Gloss/	1	pcs.	96.30	#1	96.30	103.04
5NA853687 2ZZ	Inscription Bright Chrome?	1	pcs.	92.83	#1	92.83	99.33
	TIGUAN						
5NA807421 GRU	Cover For Bumper Primed?	1	pcs.	1,151.75	#1	1,151.75	1,232.37
	REAR BUMPER						
5NA807521B 9B9	Spoiler Satin Black	1	pcs.	291.94	#1	291.94	312.38
	REAR BUMPER MID						
5NA807568C YE4	Rear Diffusor Granite Gre	1	pcs.	465.10	#1	465.10	497.66
WHT005263	Rivet	4	pcs.	1.09	#1	4.36	4.67
5NA919491A	Sensor Bracket	1	pcs.	12.60	#1	12.60	13.48
5NA919492A	Sensor Bracket	1	pcs.	12.60	#1	12.60	13.48
5NA919491	Sensor Bracket	1	pcs.	12.60	#1	12.60	13.48
5NA919492	Sensor Bracket	1	pcs.	12.60	#1	12.60	13.48
5NA919397	Sensor Bracket	1	pcs.	12.60	#1	12.60	13.48
5NA919398	Sensor Bracket	1	pcs.	12.60	#1	12.60	13.48
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	75.94	#1	75.94	81.26
D 822150A1	Bonding Agent For Plastic	1	pcs.	59.40	#1	59.40	63.56
5NA807305A	Bumper	1	pcs.	578.43	#1	578.43	618.92
	REFINFORCEMENT						
5NA807863	Attachment Strip	1	pcs.	57.67	#1	57.67	61.71
	RR CTR BRACKET						
5NA807393	Guide Piece	1	pcs.	36.24	#1	36.24	38.78
	LHR SIDE BRACKET						
5NA807394	Guide Piece	1	pcs.	36.24	#1	36.24	38.78
	RHR SIDE BRACKET						
N 90346302	Pop-Rivet	10	pcs.	1.14	#1	11.40	12.20
5NA853841 2ZZ	Decorative Moulding Brigh	1	pcs.	163.02	#1	163.02	174.43
	LHR						
5NA853842 2ZZ	Decorative Moulding Brigh	1	pcs.	166.56	#1	166.56	178.22
	RHR						
5NA853835 2ZZ	Decorative Moulding Brigh	1	pcs.	211.79	#1	211.79	226.62
	CENTRE						
5NA945105A	Reflector	1	pcs.	65.92	#1	65.92	70.53
	LHR INNER						

VOLKSWAGEN CENTRE SINGAPORE

17 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
MS
FIRSTCAPITAL INSURANCE
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Ms.
CHAN
MUN SIN
95 PRINCE CHARLES CRESCENT
#23-14
SINGAPORE 159027

Document no.
Document date 05-10-2020
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2020025254/ 1
Job order date 03-10-2020
Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SW23M	AD14PY	14-11-2018	WVGZZZ5NZJW940698	Tiguan 1.4actHLBMTFR 110TSID6F	32,044

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5NA945103	Reflector 3?	1	pcs.	65.92	#1	65.92	70.53
5NA971104N	LHR OUTER	1	pcs.	121.94	#1	121.94	130.48
	Harness For Bumper X	5	pcs.	840.00	#1	4,200.00	4,494.00
	LABOUR	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOTLID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR WINDSCREEN	5	pcs.	800.00	#1	4,000.00	4,280.00
	Spray Painting	1	pcs.	80.00	#1	80.00	85.60
	NUMBER PLATE						
	MS FIRST CAPITAL DIRECT SETTLEMENT DOA : 02/10/2020 TP VEH : SH7929H SURVEY BY :						

Quotation valid till 10-10-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	16,174.92	7%	1,185.44	16,934.92	18,120.36

Customer

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

Signature:

Date:

Rahul
14p 900/1068

5 days

Service Advisor

07/10/2020 10/10/20

Resy before paint